

Community Living Arrangement Inspection Report Summary

Maple Avenue R-949

58B Maple Avenue Windsor, CT 06095

R-949

WILA

Inspection Date: Wednesday, July 20, 2011

DDS Region: North

Inspection Type: Standard

Inspection Report Citations Were Reported In The Following Regulatory Areas:

Regulatory Category

17a-227-11 Physical Requirements

11d Hazard prevention