



EX. 5.9 Representative Construction Photos



PHOTOGRAPHS - CONSTRUCTION PHASE



Vegetation clearing within existing right-of-way.



Vegetation clearing within existing right-of-way.



Vegetation clearing within existing right-of-way.



Cleared vegetation being used for wetland matting.



Test bore for soil conditions.



Construction equipment access road.

PHOTOGRAPHS - CONSTRUCTION PHASE



Construction equipment access road.



Boring foundation for pole structure.



Installation of bolts for pole structure.



Installing pole structure on foundation.



Assembly of pole structure.



New H-framed being installed.

PHOTOGRAPHS – CONSTRUCTION PHASE



Installation of overhead pole structures



Installation of pole structures



Construction activity at substation.



Construction activity at substation.



Temporary work space along right-of-way.



Restoration.