

WETLAND IMPACT ASSESSMENT PHOTO LOG

**THE UNITED ILLUMINATING COMPANY
OPERATIONS CENTER SITE
100-110 AND 114 MARSH HILL ROAD
ORANGE, CONNECTICUT**

September 8, 2009

MMI #2982-02-9

Prepared for:

The United Illuminating Company

Prepared by:

MILONE & MACBROOM, INC.
99 Realty Drive
Cheshire, Connecticut 06410
(203) 271-1773
www.miloneandmacbroom.com

Photos taken September 4, 2009.



Photo 1 of 3: "Dry" wetland at W-1 through W-18.
Dominant plants are upland or facultative species.



Photo 2 of 3.




Photo 3 of 3: Riprap slope supporting former cinema parking in background (near W-4).



Photo 1 of 2: Base of retaining wall at W-8 showing very thin understory.



Photo 2 of 2.



Retaining wall at W-111a showing predominance of upland species and thin groundcover.



"Dry" wetlands near W-120a.




Drainage outlet from parking lots (near W-123a) supplies intermittent hydrology.



Photo 1 of 2: Intermittent watercourse at W-149
near proposed widening of access drive.



Photo 2 of 2: Intermittent watercourse at W-149.



Man-made pond below intermittent watercourse will be protected.



Runoff from cinema parking lots was filtered through a broad vegetated swale.



Runoff from cinema parking lots enters the retention pond via a concrete pipe.



A view of part of the retention pond from the south side near the outfall.



The retention pond exits through a control structure.



The retention pond exits into a small watercourse flowing off site to the south.



A large snapping turtle in the retention pond. Painted turtles were also observed.

2982-02-9-s809-1-rpt.doc