

56 Prospect Street P.O. Box 270 Hartford, CT 06141-0270

Kathleen M. Shanley Manager – Transmission Siting Tel: 860-728-4527

January 11, 2019

Mr. James J. Murphy, Jr., Acting Chairman Connecticut Siting Council Ten Franklin Square New Britain, CT 06051

RE: Docket No. 461A: Greenwich Substation and Line Project Monthly Construction Progress Report –December 2018

Dear Acting Chairman Murphy:

Pursuant to RCSA Section 16-50j-62(b)(3) and as described in Volume 1 – Part 1 (Cos Cob Substation Modifications) Section F.3 and Volume 1 – Part 2A (Demolition of Warehouse Building and Pre-Construction Site Preparation) Section F.3 of the *Greenwich Substation and Line Project (Project) Development and Management (D&M) Plan*, The Connecticut Light and Power Company doing business as Eversource Energy (Eversource) hereby provides to the Connecticut Siting Council ("Council") this Project Construction Progress Report for the month of December 2018.

This Construction Progress Report pertains to work at the Cos Cob Substation and the progress of the 290 Railroad Avenue warehouse building demolition).

Should you or other Council members have any questions regarding this submission, please do not hesitate to contact me via e-mail at <u>kathleen.shanley@eversource.com</u> or telephone at (860) 728-4527.

Sincerely,

Kathleen M. Shanley

Enclosure

DOCKET NO. 461A GREENWICH SUBSTATION AND LINE PROJECT MONTHLY CONSTRUCTION PROGRESS REPORT DECEMBER 2018

1. COS COB SUBSTATION

The following work was completed:

- Maintenance of erosion and sedimentation controls, as appropriate.
- Installation of foundations
- Installation of driveway curbing
- Installation of ground grid and electrical conduits
- Installation of electrical equipment as appropriate.
- The continued excavation of site to finished grade in addition to the removal of excess material to an approved facility.

Table 1 (in Attachment 1) illustrates the status of the substation work as of December 2018

2. 290 RAILROD WAREHOUSE DEMOLTION

The following work was completed:

• Capped domestic water main to the building

Table 1 (in Attachment 2) illustrates the status of the demolition work as of December 2018.

ATTACHMENT 1

Table 1 Substation Construction Progress (December 31, 2018)

Substation Location	Project Activity (% Complete)						
	Cos Cob Substation Work						
	Construction Start Date	Site Preparation/Development	Foundation Installation	Steel Erection	Electrical Equipment Installation	Testing/Energization	
Cos Cob	5/12/2018	80%	90%	57%	45%	45%	

ATTACHMENT 2

Table 1 Demolition Construction Progress (December 31, 2018)

Site Location	Project Activity (% Complete)						
	290 Railroad Warehouse Demolition						
	Construction Start Date	Site Preparation/Development	Hazardous Material Abatement	Structural Demolition			
290 RR Ave	9/11/2018	50%	26%	1%			