



## **Memorandum**

**To:** Dr. Michael Klemens

**From:** Roger Hurlbut *Roger Hurlbut*

**Date:** June 15, 2012

**Re:** Wind Colebrook South

---

Attached are environmental erosion and sediment control monitoring reports numbers 31 and 32 for the period June 1 through June 15, 2012.

Both inspections were undertaken after rain events. No problems or discharges were observed.

CC C Jones Civil 1  
G Zupkus BNE Energy

| General Information  |  |                   |                  |
|--|--|-------------------|------------------|
| Project Name:  | Wind Colebrook South   |                   |                  |
| Location:  | Winsted- Norfolk Road<br>Colebrook, Connecticut  |                   |                  |
| CT DEP Tracking No.  | CSC Petition 983   | Report No.        | 31               |
| Date of Inspection:  | June 3, 2012   | Start / End Time: | 8:15AM to 9:10AM |
| Inspector's Name(s):   | Roger Hurlbut <i>Roger Hurlbut</i>   |                   |                  |
| Inspector's Title(s):  | Project Engineer   |                   |                  |
| Inspector's Contact Information:   | LENARD ENGINEERING INC<br>860 379-6669 off   |                   |                  |
| Describe present phase of construction:  | No work has occurred since last inspection on 5/31/12<br>No problems observed  |                   |                  |
| Type of Inspection:  | <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event |                   |                  |
| Weather Information  |  |                   |                  |
| Has it rained since the last inspection?<br><input checked="" type="checkbox"/> Yes <input type="checkbox"/> No                                    |  |                   |                  |
| If yes, provide:<br>Storm Start Date & Time: 6/2 3:30 AM   Storm Duration (hrs): 11   Approximate Rainfall (in): 0.58+/-                           |  |                   |                  |
| Weather at time of this inspection? Sunny light breeze 59° F   |  |                   |                  |
| Discharge Information (A)  |  |                   |                  |
| Do you suspect that discharges may have occurred since the last inspection?<br><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |  |                   |                  |
| Are there any discharges at the time of inspection?<br><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No                         |  |                   |                  |
| Describe location of any discharges from the site:   |  |                   |                  |

| General Information  |  |                   |                   |
|--|--|-------------------|-------------------|
| Project Name:  | Wind Colebrook South   |                   |                   |
| Location:  | Winsted- Norfolk Road<br>Colebrook, Connecticut  |                   |                   |
| CT DEP Tracking No.  | CSC Petition 983   | Report No.        | 32                |
| Date of Inspection:  | June 13, 2012  | Start / End Time: | 11:00AM to 11:55M |
| Inspector's Name(s):   | Roger Hurlbut <i>Roger Hurlbut</i>   |                   |                   |
| Inspector's Title(s):  | Project Engineer   |                   |                   |
| Inspector's Contact Information:   | LENARD ENGINEERING INC<br>860 379-6669 off   |                   |                   |
| Describe present phase of construction:  | No work has occurred since last inspection on 6/3/12<br>No problems observed, grass is growing   |                   |                   |
| Type of Inspection:  | <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event |                   |                   |
| Weather Information  |  |                   |                   |
| Has it rained since the last inspection?<br><input checked="" type="checkbox"/> Yes <input type="checkbox"/> No                                    |  |                   |                   |
| If yes, provide:<br>Storm Start Date & Time: 6/11 3:15 PM   Storm Duration (hrs): 19   Approximate Rainfall (in): 0.75                             |  |                   |                   |
| Weather at time of this inspection? overcast light breeze 62° F  |  |                   |                   |
| Discharge Information (A)  |  |                   |                   |
| Do you suspect that discharges may have occurred since the last inspection?<br><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |  |                   |                   |
| Are there any discharges at the time of inspection?<br><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No                         |  |                   |                   |
| Describe location of any discharges from the site:   |  |                   |                   |