

General Information				
Project Name:	Wind Colebrook South			
Location:	Winsted- Norfolk Road Colebrook, Connecticut			
CT DEP Tracking No.	CSC Petition 983	Report No.	1	
Date of Inspection:		Start / End Time:	2PM	3.20 PM
Inspector's Name(s):	Roger Hurlbut <i>Roger Hurlbut</i>			
Inspector's Title(s):				
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off 860 208-1351 cell			
Describe present phase of construction:	Tree cutting only, no excavation No E&S controls in place			
Type of Inspection: <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event				
Weather Information				
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, provide: Storm Start Date & Time:                      Storm Duration (hrs):                      Approximate Rainfall (in): 11/7/2011 8 Am                                      20 Hrs    2+/- in				
Weather at time of this inspection? Cool 35°F partly cloudy to overcast				
Discharge Information (A)				
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No    Normal runoff - no obvious sediment or erosion				
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No    Normal runoff - no obvious sediment or erosion				
Describe location of any discharges from the site:				

