



Memorandum

To: Dr. Michael Klemens
From: Roger Hurlbut *Roger Hurlbut*
Date: Sept 7, 2012
Re: Wind Colebrook South

Attached are environmental erosion and sediment control monitoring reports numbers 47 and 48 for the period Aug 25 through Sept 7, 2012.

Both inspections were after rainfall events. No problems or discharges were observed.

CC C Jones Civil 1
G Zupkus BNE Energy

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	47
Date of Inspection:	Aug 28, 2012	Start / End Time:	6:30:PM to 7:15 PM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off		
Describe present phase of construction:	No problems observed No work has been done since last inspection on 8-23-12		
Type of Inspection: <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, provide: Storm Start Date & Time: 8/28/12 6AM Storm Duration (hrs): 3 Approximate Rainfall (in): 0.8			
Weather at time of this inspection? 70° F, clear			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	48
Date of Inspection:	Sept 5, 2012	Start / End Time:	6:45:PM to 7:30 PM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off		
Describe present phase of construction:	No problems observed No work has been done since last inspection on 8-28-12		
Type of Inspection: <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, provide: Storm Start Date & Time: 9/4/12 11PM Storm Duration (hrs): 10 Approximate Rainfall (in): >0.75			
Weather at time of this inspection? 78° F, clear			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			