## **Memorandum**

**To:** Dr. Michael Klemens

From: Roger Hurlbut Roger How but

**Date:** May 2, 2014

**Re:** BNE Wind Colebrook South

Attached are environmental erosion and sediment control monitoring reports numbers 145 thru 147 for the period April 19 thru May 2, 2014.

No runoff occurred as a result of the recent rain events.

CC G Zupkus BNE Energy

| General Information   |  |                   |                     |  |  |
|---|--|-------------------|---------------------|--|--|
| Project Name:   | Wind Colebrook South   |                   |                     |  |  |
| Location:   | Winsted- Norfolk Road  |                   |                     |  |  |
|   | Colebrook, Connecticut   | D (N              | 4.4                 |  |  |
| CT DEP Tracking No.   | CSC Petition 983   | Report No.        | 145                 |  |  |
| Date of Inspection:   | April 24, 2014   | Start / End Time: | 12:35 PM to 1:10 PM |  |  |
| Inspector's Name(s):  | Roger Hurlbut  |                   |                     |  |  |
| Inspector's Title(s):   | Project Engineer   |                   |                     |  |  |
| Inspector's Contact<br>Information:   | LENARD ENGINEERING INC<br>860 379-6669 off ice   |                   |                     |  |  |
| Describe present phase of construction:   | Site 2 location has been partially seeded and silt fence installed at eastern edge Of disturbed area.  Site 1 detention basins have been seeded. |                   |                     |  |  |
| Type of Inspection: ☑Regular □Pre-storm e   | vent   | ent □Post-storm € | event               |  |  |
| Weather Information   | _  |                   |                     |  |  |
| Has it rained since the last ins ☐ Yes ☑No  | pection?   |                   |                     |  |  |
| If yes, provide: Storm Start Date & Time: Storm Duration (hrs): Approximate Rainfall: |  |                   |                     |  |  |
| Weather at time of this inspection? 56° Sunny Windy                                   |  |                   |                     |  |  |
| Discharge Information (A)   |  |                   |                     |  |  |
| Do you suspect that discharges may have occurred since the last inspection?  □Yes ☑No |  |                   |                     |  |  |
| Are there any discharges at the time of inspection?  ☐Yes ☐No                         |  |                   |                     |  |  |
| Describe location of any discharges from the site:                                    |  |                   |                     |  |  |

| General Information   |  |                   |                    |  |  |
|---|--|-------------------|--------------------|--|--|
| Project Name:   | Wind Colebrook South   |                   |                    |  |  |
| Location:   | Winsted- Norfolk Road  |                   |                    |  |  |
|   | Colebrook, Connecticut   | D (N              | 446                |  |  |
| CT DEP Tracking No.   | CSC Petition 983   | Report No.        | 146                |  |  |
| Date of Inspection:   | April 28, 2014   | Start / End Time: | 7:30 AM to 8:00APM |  |  |
| Inspector's Name(s):  | Roger Hurlbut  |                   |                    |  |  |
| Inspector's Title(s):   | Project Engineer   |                   |                    |  |  |
| Inspector's Contact Information:  | LENARD ENGINEERING INC<br>860 379-6669 off ice   |                   |                    |  |  |
| Describe present phase of construction:   | Seed has sprouted Unable to get to site on 4/27 due to detour from traffic accident & pole replacement |                   |                    |  |  |
| Type of Inspection:  □Regular □Pre-storm event □ During storm event □Post-storm event   |  |                   |                    |  |  |
| Weather Information   |  |                   |                    |  |  |
| Has it rained since the last inspection?  ☑ Yes □No  If yes, provide: Storm Start Date & Time:4/26/14 2:30 AM Storm Duration (hrs): 8+3 Approximate Rainfall: >1.0" |  |                   |                    |  |  |
|   |  |                   |                    |  |  |
| Weather at time of this inspection? 37° Sunny Windy   |  |                   |                    |  |  |
| Discharge Information (A)   |  |                   |                    |  |  |
| Do you suspect that discharges may have occurred since the last inspection?  □Yes □No   |  |                   |                    |  |  |
| Are there any discharges at the time of inspection?  ☐Yes ☐No   |  |                   |                    |  |  |
| Describe location of any discharges from the site:  |  |                   |                    |  |  |
|   |  |                   |                    |  |  |
|   |  |                   |                    |  |  |

| General Information   |  |                   |                  |  |  |
|---|--|-------------------|------------------|--|--|
| Project Name:   | Wind Colebrook South                           |                   |                  |  |  |
| Location:   | Winsted- Norfolk Road                          |                   |                  |  |  |
| CT DEP Tracking No.   | Colebrook, Connecticut CSC Petition 983        | Report No.        | 147              |  |  |
| Date of Inspection:   | May 1, 2014                                    | Start / End Time: | 4:30PM to 5:00PM |  |  |
| Inspector's Name(s):  | Roger Hurlbut                                  |                   |                  |  |  |
| Inspector's Title(s):   | Project Engineer                               |                   |                  |  |  |
| Inspector's Contact<br>Information:   | LENARD ENGINEERING INC<br>860 379-6669 off ice |                   |                  |  |  |
| Describe present phase of construction:   | No work on site                                |                   |                  |  |  |
| Type of Inspection:  □Regular □Pre-storm event □ During storm event □Post-storm event   |  |                   |                  |  |  |
| Weather Information   |  |                   |                  |  |  |
| Has it rained since the last ins  | pection?                                       |                   |                  |  |  |
| <ul> <li>✓ Yes □No</li> <li>If yes, provide:</li> <li>Storm Start Date &amp; Time4/30/14 4 AM Storm Duration (hrs): 29 Approximate Rainfall: &gt;2.9</li> </ul> |  |                   |                  |  |  |
| Weather at time of this inspection? 70° Sunny Windy   |  |                   |                  |  |  |
| Discharge Information (A)   |  |                   |                  |  |  |
| Do you suspect that discharges may have occurred since the last inspection?  ☐Yes ☐No   |  |                   |                  |  |  |
| Are there any discharges at the time of inspection?  □Yes ☑No   |  |                   |                  |  |  |
| Describe location of any discharges from the site:  |  |                   |                  |  |  |