

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	160
Date of Inspection:	August 1, 2014	Start / End Time:	8:00 AM to 8:30 AM
Inspector's Name(s):	Todd Parsons		
Inspector's Title(s):	Principal Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	No work on site		
Type of Inspection:	<input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event		
Weather Information			
Has it rained since the last inspection?			
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
If yes, provide:			
Storm Start Date & Time 7/28/14 3:00 AM		Storm Duration 20 hrs on and off	Approximate Rainfall: 0.95-in
Weather at time of this inspection? 70° Cloudy			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			