



## Memorandum

**To:** Dr. Michael Klemens  
**From:** Roger Hurlbut *Roger Hurlbut*  
**Date:** Nov 2, 2014  
**Re:** BNE Wind Colebrook South

---

Attached are environmental erosion and sediment control monitoring reports numbers 173 and 174 for the period Oct 16 ,2014 thru October 31, 2014

No work on site & areas are stable

CC Greg Zupkus BNE Energy

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	<b>173</b>
Date of Inspection:	Oct 23, 2014	Start / End Time:	7:15AM to 7:45 AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	No work on site		
Type of Inspection: <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input checked="" type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, provide: Storm Start Date & Time Oct 22 3:30PM    Storm Duration 24 Hrs    Approximate Rainfall: >1			
Weather at time of this inspection? 48° Light Rain			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	<b>174</b>
Date of Inspection:	Oct 31, 2014	Start / End Time:	4:45PM to 5:15PM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	No work on site		
Type of Inspection: <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input checked="" type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, provide: Storm Start Date & Time Oct 26 2:30Am    Storm Duration 2 Hrs    Approximate Rainfall: >0.12			
Weather at time of this inspection? 45 Overcast			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			