



Lenard Engineering Inc. Civil, Environmental, and Hydrogeological Consultants

140 Willow Street – Suite #8 Winsted, CT 06098

Tel: 860-379-6669

Fax: 860-738-1272

Memorandum

To: Dr. Michael Klemens

From: Roger Hurlbut *Roger Hurlbut*

Date: Nov 14, 2014

Re: BNE Wind Colebrook South

Attached are environmental erosion and sediment control monitoring reports numbers 175 and 176 for the period Nov 1, 2014 thru Nov 14, 2014

No work on site & areas are stable

CC Greg Zupkus BNE Energy

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	175
Date of Inspection:	Nov 7, 2014	Start / End Time:	7:15AM to 7:45AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	No work on site		
Type of Inspection:	<input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event		
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
If yes, provide: Storm Start Date & Time Nov 6 1:15PM Storm Duration 5 Hrs Approximate Rainfall: >0.25			
Weather at time of this inspection? 39 Overcast			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	176
Date of Inspection:	Nov 13, 2014	Start / End Time:	7:15AM to 7:45AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	No work on site		
Type of Inspection:	<input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event		
Weather Information			
Has it rained since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
If yes, provide: Storm Start Date & Time Storm Duration Approximate Rainfall:			
Weather at time of this inspection? 29 Overcast			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			