



**Lenard Engineering Inc. Civil, Environmental, and Hydrogeological Consultants**

140 Willow Street – Suite #8 Winsted, CT 06098

Tel: 860-379-6669

Fax: 860-738-1272

## **Memorandum**

**To:** Dr. Michael Klemens

**From:** Roger Hurlbut *Roger Hurlbut*

**Date:** February 2, 2015

**Re:** BNE Wind Colebrook South

---

Attached are environmental erosion and sediment control monitoring reports numbers 190 and 11 for the period Feb 7, 2015 thru Feb 20, 2015

Ground is frozen & snow covered.

It appears the layout and or exploration work is being undertaken.

CC Greg Zupkus BNE Energy

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	<b>190</b>
Date of Inspection:	February 13, 2015	Start / End Time:	7:15 AM to 7:45AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	No work on site Ground is frozen & snow covered		
Type of Inspection:	<input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event		
Weather Information			
Has it rained since the last inspection?			
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
If yes, provide:			
Storm Start Date & Time		Storm Duration	Approximate Rainfall
Weather at time of this inspection?    -2°F    Sunny			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	<b>191</b>
Date of Inspection:	February 20, 2015	Start / End Time:	7:15 AM to 7:45AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	Ground is frozen & snow covered Layout and exploration work is being undertaken		
Type of Inspection:	<input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event		
Weather Information			
Has it rained since the last inspection?			
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
If yes, provide:			
Storm Start Date & Time		Storm Duration	Approximate Rainfall
Weather at time of this inspection?    --2°F    Sunny			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			