



Lenard Engineering Inc. Civil, Environmental, and Hydrogeological Consultants

140 Willow Street – Suite #8 Winsted, CT 06098

Tel: 860-379-6669

Fax: 860-738-1272

Memorandum

To: Dr. Michael Klemens

From: Roger Hurlbut *Roger Hurlbut*

Date: April 2, 2015

Re: BNE Wind Colebrook South

Attached are environmental erosion and sediment control monitoring reports numbers 196 and 197 for the period March 21, 2015 thru April 3, 2015

Conditions are stable, ground at site is beginning to thaw and snow is melting.

CC Greg Zupkus BNE Energy

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	196
Date of Inspection:	March 27, 2015	Start / End Time:	7:30 AM to 8:00AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	Ground is frozen & partially snow covered		
Type of Inspection:	<input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input checked="" type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event		
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
If yes, provide: Storm Start Date & Time 3/26/15 12:30PM Storm Duration >18 hrs Approximate Rainfall 0.39 in			
Weather at time of this inspection? 28°F Pt Cldy snow showers			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	197
Date of Inspection:	April 2, 2015	Start / End Time:	11:30 AM to 12:00PM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	Ground is thawing & partially snow covered Conditions at site are stable		
<p>Type of Inspection:</p> <input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
If yes, provide:			
Storm Start Date & Time	Storm Duration	Approximate Rainfall	
Weather at time of this inspection? 52°F sunny			
Discharge Information			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			