

July 19, 2024

Attorney Melanie Bachman Acting Executive Director Connecticut Siting Council Ten Franklin Square New Britain, CT 06501

EM-T-MOBILE-001-240214
T-Mobile Site ID CT11501E
122 - Rt. 6 Andover,CT
Notice of Compliance with Conditions and Construction Completion

Dear Attorney Bachman:

The T-Mobile site referenced above was approved by The Connecticut Siting Council (Council) on March 4, 2024 as an Exempt Modification. T-Mobile is now requesting the close out of the approval and hereby acknowledges the following conditions were met:

- 1. Approval of any changes be delegated to Council staff;
- 2. Site preparation and construction activities shall occur during the time period of November 1 through March 31 consistent with Condition No. 2 of the Council's August 9, 2021 re-issued Decision and Order in Docket No. 242;
- 3. Antenna mount modifications, antennas and equipment shall be installed in accordance with the Mount Analysis prepared by Trylon last revised September 8, 2023 and stamped and signed by Matthew K. Jamerson;
- 4. Within 45 days following completion of equipment installation, T-Mobile shall provide documentation certified by a Professional Engineer that its installation complied with the recommendations of the Mount Analysis;
- 5. RF access restriction and caution signage shall be installed at the site in compliance with FCC guidance;
- 6. Deployment of any 5G services must comply with FCC and FAA guidance relative to air navigation, as applicable;

- 7. Any deviation from the proposed modification as specified in this notice and supporting materials submitted to the Council shall render this acknowledgement invalid;
- 8. The Council shall be notified in writing at least two weeks prior to the commencement of site construction activities;
- 9. Within 45 days after completion of construction, the Council shall be notified in writing that construction has been completed along with a representative photograph of the facility modification;
- 10. Any nonfunctioning antenna and associated antenna mounting equipment, or other equipment at this facility owned and operated by T-Mobile shall be removed within 60 days of the date the antenna or equipment ceased to function;
- 11. The validity of this action shall expire one year from the date of this letter; and
- 12. T-Mobile may file a request for an extension of time beyond the one year deadline provided that such request is submitted to the Council not less than 60 days prior to the expiration.

The attached PE Closeout Letter dated May 23, 2024 provides evidence of compliance with the conditions outlined by the Council. In addition, T-Mobile hereby notifies the Council that construction of the acknowledged modifications was completed as of May 16, 2024, please find attached photos of the completed modifications to this facility.

Sincerely,

Victoria Masse

Zoning and Permitting

Victoria Masse

Northeast Site Solutions



Final Report of Special Inspections

Project: CT11501E (T-Mobile Anchor Project) Date: May 23, 2024

Crown Id: 842856

Location: 122 Jonathan Trumbull Hwy., Andover, CT

Owner: T-Mobile Northeast LLC

Engineer of Record: Derek J. Creaser, P.E.

Centerline Communications, LLC.

To the best of my information, knowledge and belief, the Special Inspections required for this project, and itemized in the *Statement of Special Inspections* submitted for permit, have been performed and all discovered discrepancies have been reported and resolved.

Representatives of Centerline Communications, LLC performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on May 10, 2024.

Based on my knowledge, information, and belief the T-Mobile Installation substantially conforms to the approved plans, IBC 2021, 2022 CT State Building Code, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-H), and the following:

1. Final Construction Drawings dated 01/30/24 prepared by PM&A.

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications.

This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation.

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted, Special Inspector

Derek Creaser, P.E.
Director of A&E
Centerline Communications
dcreaser@clinellc.com







