

**From:** [Tatasciore, Domenica](#)  
**To:** [CSC-DL Siting Council](#)  
**Cc:** [Fontaine, Lisa](#)  
**Subject:** EM-VER-007-211213 - 240 Kensington Road, Berlin, CT - 826217\_589572  
**Date:** Thursday, August 10, 2023 9:41:37 AM  
**Attachments:** [Engineering Letter.pdf](#)  
[EM-VER-007-211213 - 240 Kensington Road, Berlin, CT - 826217\\_589572.pdf](#)

---

Good morning,

This email is to confirm the Verizon installation has been completed.  
Please let me know if you have any questions

Thanks,

**DOMENICA TATASCIORE**

Site Acquisition Specialist

T: 508-621-9161

**CROWN CASTLE**

1800 West Park Drive, Westborough, MA 01581

CrownCastle.com

This email may contain confidential or privileged material. Use or disclosure of it by anyone other than the recipient is unauthorized. If you are not an intended recipient, please delete this email.



September 20, 2022

Robert Brodka  
Crown Castle  
2000 Corporate Drive  
Canonsburg, PA 15317  
(724) 416-2000

B&T Engineering, Inc.  
1717 S. Boulder, Suite 300  
Tulsa, OK 74119  
(918) 587-4630  
btwo@btgrp.com

**Subject:** Construction Completion Letter

**Carrier Designation:** Site Name: Berlin

**Engineering Firm Designation:** B+T Group Project Number: 87581.031.01

**Site Data:** 240 Kensington Road, Berlin, CT 06037  
Latitude 41.626194°, Longitude -72.775647°  
Monopole

Dear Robert

B&T Engineering is pleased to submit this “Construction Completion Letter” regarding the above-mentioned Monopole.

We reviewed the photographs of the telecommunications equipment installed on the Monopole, taken on September 8, 2022. Based on the photographs provided, As Built by Chris J dated September 13, 2022, and the construction drawings by B+T Group dated November 10, 2021, this telecommunications site has the following antennas and associated equipment installed in three sectors on the Monopole.

- (3) New Antennas
- (1) New OVP- 12 Pendant
- (1) New Kicker Kit
- (3) New Support Rail Corner Bracket
- (3) New Support Rail


The quantities and types of antennas and associated equipment from the photographs are in structural compliance, therefore, it is our opinion that the antennas and associated equipment were properly installed.

We at B&T Engineering appreciate the opportunity of providing our continuing professional services to you and Crown Castle. If you have any questions or need further assistance on this or any other projects, please give us a call.

Construction Control Inspection Letter prepared by: Jennifer Tillson, E.I.

Respectfully submitted by: B&T Engineering, Inc. (COA PEC.0001564 Exp. 2/1/23)

Chad Tuttle, P.E.  
Engineer of Record





May 12, 2023 at 5:11:16 PM

34 Hall Ln

Berlin, CT 06037

United States