

---

**From:** Aja Chase <aja.chase@ericsson.com>  
**Sent:** Friday, January 12, 2024 11:57 AM  
**To:** CSC-DL Siting Council  
**Subject:** EM-AT&T-015-230316  
**Attachments:** CT5093 - FSOSI - 1.9.2024.pdf; 10070948.NYC-NJ\_Photos.231228.CTL05093.Post\_Construction\_Photos-Bulk.(Not\_specified).jpg

Good Afternoon CSC,

Cx on this site below is now completed and a photo of the work completed is attached. Please advise if you need anything else!

CTL05093	MRCTB057463	1320 CHOPSEY HILL ROAD	BRIDGEPORT	06606	EM-AT&T-015-230316
----------	-------------	------------------------	------------	-------	--------------------

Thanks,

Aja

## Final Report of Special Inspections

Project: AT&T: CTL5093 (FA: 10070948) / ATC: 383598

Location: 1000 Trumbull Avenue, Bridgeport, CT 06606

Owner: Carrier: AT&T Mobility / Tower: American Tower Corporation

Engineer of Record: Daniel P. Hamm, P.E.

Tower Engineering Professionals, LLC (TEP OPCO, LLC)

To the best of my information, knowledge and belief, the Special Inspections required by Chapter 17 for the project have been performed and all discovered discrepancies have been reported and resolved.

Representatives of TEP Northeast performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on December 28, 2023.

Based on my knowledge, information and belief the wireless installation substantially conforms to the approved plans, IBC 2021 with 2022 CT State Building Code Amendments, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-H), and the following:

1. Final Rev. 1 Construction Drawings dated 03/29/2023, prepared by Tower Engineering Professionals, entitled "AT&T Mobility Antenna Amendment Plan."
2. Final Mount Analysis dated 01/25/2023, prepared by American Tower Corporation.
3. Final Structural Analysis dated 01/27/2023, prepared by American Tower Corporation.

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications. This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation.

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,  
Special Inspector

Daniel P. Hamm, P.E.



Signature

01/09/24

Date



Licensed Professional  
Seal

December 5, 2023  
1000 Trumbull Ave  
Bridgeport CT 06602  
United States

