

From: Aja Chase <aja.chase@ericsson.com>
Sent: Wednesday, August 23, 2023 10:37 AM
To: CSC-DL Siting Council <Siting.Council@ct.gov>
Subject: EM-AT&T-017-220725

Good Afternoon CSC,

Please find the letter from the Engineer on the below site, as construction is now complete. A photo of the overall work completed is also attached. Please reach out if you have any questions!

1 WILLIS STREET	BRISTOL	06010
-----------------	---------	-------


ERICSSON
Aja Chase
Construction Manager
AT&T NE Market
401-952-6205

Final Report of Special Inspections

Project: CT1055 (FA: 10035029)

Location: 790 Willis Street, Bristol, CT 06010-7269

Owner: Carrier; AT&T Mobility / Tower: American Tower Corporation

Engineer of Record: Daniel P. Hamm, P.E.

Tower Engineering Professionals, LLC (TEP OPCO, LLC)

To the best of my information, knowledge and belief, the Special Inspections required by Chapter 17 for the project have been performed and all discovered discrepancies have been reported and resolved.

Representatives of TEP Northeast performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on July 12, 2023.

Based on my knowledge, information and belief the wireless installation substantially conforms to the approved plans, IBC 2015 with 2018 CT State Building Code Amendments, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-H), and the following:

1. Final Rev. 0 Construction Drawings dated 05/18/2022, prepared by Hudson Design Group LLC, entitled "AT&T 5G NR 1SR CBAND AMENDMENT PLAN."
2. Final Post Modification Mount Analysis Report dated 04/18/2022, prepared by American Tower Corporation.

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications. This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation.


Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,
Special Inspector

Daniel P. Hamm, P.E.
(Type or print name)

Signature

Date



jul. 6, 2023, 2:10:10 p.m.
790 Willis St
Bristol CT 06010
Estados Unidos

