

**From:** Aja Chase <aja.chase@ericsson.com>  
**Sent:** Wednesday, January 17, 2024 12:02 PM  
**To:** CSC-DL Siting Council <Siting.Council@ct.gov>  
**Subject:** EM-CING-043-210430

Good Afternoon CSC,

Please find FCCA completed for the site below. This was an older site, please advise if you need anything additional.

10578403	CT3438	MRCTB045175	100 Sunset Ridge Drive	East Hartford
----------	--------	-------------	------------------------	---------------

Thank you!

Aja

## Final Report of Special Inspections

Project: CT3438

Location: 100 Sunset Ridge, East Hartford, CT 06108

Owner: AT&T

Engineer of Record: Daniel P. Hamm, P.E.

TEP Northeast/ TEP OPCO, LLC

To the best of my information, knowledge and belief, the Special Inspections required by Chapter 17 for the project have been performed and all discovered discrepancies have been reported and resolved.

Representatives of TEP Northeast performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on December 1, 2022.

Based on my knowledge, information, and belief the wireless installation substantially conforms to the approved plans, IBC 2015 with 2018 CT State Building Code Amendments, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-H), and the following:

1. Final Construction Drawings dated 07/13/2022, prepared by TEP Northeast, entitled "5G NR 1SR CBAND, 5G NR RADIO, 2022 UPGRADE"
2. Final Mount Analysis dated 04/08/2022 prepared by TEP Northeast
3. Final Structural Analysis dated 05/25/2022, prepared by TEP Northeast.

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications. This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation.

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,  
Special Inspector

Daniel P. Hamm, P.E.  
(Type or print name)

A handwritten signature in black ink, appearing to read 'D. Hamm', written over a horizontal line.

Signature

12/01/2022

Date

