



 750 W Center Street
Suite 301
West Bridgewater, MA 02379
 info@clinellc.com
 1-(844)-748-8878

T-Mobile
Cullen Morgan
Site Acquisition Consultant
750 W Center Street
Suite 301
West Bridgewater, MA 02379
(941) 549-7263
cmorgan@clinellc.com

March 8, 2023

ATTN: Melanie A. Bachman, Executive Director
Connecticut Siting Council
10 Franklin Square
New Britain, Connecticut 06051

**RE: Commencement of Construction Activity – EM-T-MOBILE-049-210910
37 Bacon Road, Enfield, CT 06082**

Dear Ms. Bachman:

The purpose of this letter is to notify the Siting Council that the construction activity associated with the above-referenced T-Mobile telecommunications facilities has been completed.

If you have any questions or need any additional information regarding these facilities, please do not hesitate to contact me.

Respectfully,

Cullen Morgan
Site Acquisition Consultant
Centerline Communications, LLC (Agent to T-Mobile)
Mobile: (941) 549-7263
cmorgan@clinellc.com



HUDSON
Design Group LLC

Final Report of Special Inspections

Project: CT11533B (L600 & Anchor Program)

Location: 37 Bacon Rd. Enfield, CT 06082

Owner: T-Mobile

Engineer of Record: Daniel P. Hamm, P.E.

Hudson Design Group, LLC.

To the best of my information, knowledge and belief, the Special Inspections required by Chapter 17 for the project have been performed and all discovered discrepancies have been reported and resolved.

Representatives of Hudson Design Group LLC performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on February 24, 2022.

Based on my knowledge, information, and belief the wireless installation substantially conforms to the approved plans, IBC 2015 with 2018 CT State Building Code Amendments, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-G), and the following:

1. Final Construction Drawings dated 8/2/2021, prepared by Hudson Design Group LLC, entitled "CT533 / SAI-Enfield)."
2. Final Mount Analysis dated 7/27/2021, prepared by Hudson Design Group LLC
3. Final Structural Analysis dated 7/21/2021, prepared by Hudson Design Group LLC.


All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications. This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation.

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,
Special Inspector

Daniel P. Hamm, P.E.

(Type or print name)


Signature

2/25/2022

Date

