
From: Aja Chase <aja.chase@ericsson.com>
Sent: Friday, January 12, 2024 11:39 AM
To: CSC-DL Siting Council
Subject: EM-AT&T-064-221027
Attachments: CT1011 - FSOSI - 12.28.2023.pdf; Alpha from ground 1.jpg

Good Afternoon CSC,

Please find the attached FCCA letter and a photo of the work completed attached on the site below. If you have any additional questions, please let me know. Thank you!

CTL01011	MRCTB051290	289 H MOUNTAIN STREET	HARTFORD	06106	EM-AT&T-064-221027
----------	-------------	-----------------------	----------	-------	--------------------

Kindly,

Aja

Final Report of Special Inspections

Project: AT&T: CTL01011 (FA: 10034968) / ATC: 302481 (FCC: 1064828)

Location: 289 Mountain Street, Hartford, CT 06106-4121

Owner: Carrier: AT&T Mobility / Tower: American Tower Corporation

Engineer of Record: Daniel P. Hamm, P.E.

Tower Engineering Professionals, LLC (TEP OPCO, LLC)

To the best of my information, knowledge and belief, the Special Inspections required by Chapter 17 for the project have been performed and all discovered discrepancies have been reported and resolved.

Representatives of TEP Northeast performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on November 28, 2023.

Based on my knowledge, information and belief the wireless installation substantially conforms to the approved plans, IBC 2015 with 2018 CT State Building Code Amendments, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-H), and the following:

1. Final Rev. 1 Construction Drawings dated 10/22/2020, prepared by TEP Northeast (TEP OPC, LLC), entitled "AT&T 5G NR / 5G NR 1SR CBAND / BBU RECONFIGURATION / 5G NR UPGRADE / 4TXRC ANTENNA RETORFIT AMENDMENT PLAN."
2. Final Antenna Mount Analysis dated 04/05/2022, prepared by Power of Design.
3. Final Structural Analysis dated 06/27/2022, prepared by American Tower Corporation.

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications. This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,
Special Inspector

Daniel P. Hamm, P.E.
(Type or print name)



Signature

12/28/23

Date



Oct 31, 2023 at 2:45:07 PM
200 Newington Ave
Hartford CT 06106
United States

