Robinson+Cole

KENNETH C. BALDWIN

280 Trumbull Street Hartford, CT 06103-3597 Main (860) 275-8200 Fax (860) 275-8299 kbaldwin@rc.com Direct (860) 275-8345

Also admitted in Massachusetts and New York

February 7, 2023

Melanie A. Bachman, Esq. Executive Director/Staff Attorney Connecticut Siting Council 10 Franklin Square New Britain, CT 06051

Re: EM-VER-069-220317 – Cellco Partnership d/b/a Verizon Wireless Telecommunications Facility, 79 Putnam Pike, Killingly, Connecticut

Completion of Construction

Dear Ms. Bachman:

The purpose of this letter is to notify the Siting Council that construction activity associated with the above-referenced facility modification <u>has been completed</u>.

As required by the Council's approval, attached is a letter from TEP Northeast dated January 18, 2023, verifying that Cellco's facility modifications were completed in accordance with the November 29, 2021 Mount Analysis Report by Maser Consulting.

If you have any questions or need any additional information regarding this facility, please do not hesitate to contact me.

Sincerely,

Kenneth C. Baldwin

Kunie mu

Attachment Copy to:

Karla Hanna Kamoya Baustista DeLeon



Final Report of Special Inspections

Project: Killingly Center CT

Location: 79 Putnam Pike, Dayville, CT 06241

Owner: Verizon Wireless

Engineer of Record: Daniel P. Hamm, P.E.

TEP Northeast (TEP OPCO, LLC)

To the best of my information, knowledge and belief, the Special Inspections required by Chapter 17 for the project have been performed and all discovered discrepancies have been reported and resolved.

Representatives of TEP Northeast (TEP OPCO, LLC) performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on December 15, 2022.

Based on my knowledge, information and belief the wireless installation substantially conforms to the approved plans, IBC 2015 with 2018 CT State Building Code Amendments, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-G), and the following:

- 1. Final Construction Drawings dated 01-28-2022, prepared by Hudson Design Group LLC, entitled "KILLINGLY CENTER CT (5GSB6 2021)"
- 2. Final Structural Analysis dated 01-17-2022, prepared by Hudson Design Group LLC.
- 3. Final Mount Structural Analysis dated 11-29-2021 prepared by Maser Consulting Connecticut.

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications. This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted, Special Inspector		OF CONNECTION OF
<u>Daniel P. Hamm. P.E.</u> (Type or print name)		KONTONIA KONTONIA KANDINIA KAN
Signature	Date	Licensed Professional Seal