

From: Aja Chase <aja.chase@ericsson.com>
Sent: Wednesday, October 30, 2024 2:42 PM
To: CSC-DL Siting Council <Siting.Council@ct.gov>
Subject: EM-AT&T-077-221115 *(63 Elm St, Manchester)*

Good Afternoon CSC,

Please find the FCCA and photo of overall work completed on the site below. If you need anything else, please reach out!

10071101	CTL05322	WSCTB0010582	EM-AT&T-077-221115
----------	----------	--------------	--------------------

Thanks,



Aja Chase
Senior Construction Manager
ATT NE MCA
MANA NTW RO B&O RE Construction Mgmt B
Phone: 401-952-6205



Final Report of Special Inspections

Project: CT5322 (10071101)
Location: 63 Elm Street, Manchester, CT 06040
Owner: AT&T
Engineer of Record: Daniel P. Hamm, P.E.
TEP OPCO, LLC

To the best of my information, knowledge and belief, the Special Inspections required by Chapter 17 for the project have been performed and all discovered discrepancies have been reported and resolved.

Representatives of TEP OPCO, LLC performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on October 7, 2024.

Based on my knowledge, information and belief the wireless installation substantially conforms to the approved plans, IBC 2021 with 2022 CT State Building Code Amendments, Structural Standards for Antenna Supporting Structures and Antennas (EIA/TIA-222-H), and the following:

1. Final Construction Drawings dated 1/23/2024, prepared by TEP OPCO, LLC, entitled "5G NR 1SR CBAND, 5G NR RADIO, ANTENNA MODIFICATIONS, 4TXRX SOFTWARE
2. RETROFIT, 4T4R ANTENNA RETROFIT, BBU RECONFIGURATION, LTE 7C ADD, 2025 UPGRADE"
3. Final Mount Analysis dated 5/2/2022, prepared by TEP OPCO, LLC.

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications. This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation.

Respectfully submitted,
Special Inspector

Daniel P. Hamm, P.E.
(Type or print name)

Signature

10.7.2024

Date



09/27/2024 14:34:07
N 41.7673°, W 72.5271°
CT, Manchester, West Side, Forest St
148 Forest St

