

From: Josh Costa <jcosta@clinellc.com>
Sent: Thursday, July 13, 2023 7:37 AM
To: CSC-DL Siting Council <Siting.Council@ct.gov>
Subject: RE: Palisades Drive (134 Kickapoo Road - CSC #EM-AT&T-082-221011)

All Work has been completed on site, attached is a copy of the engineers letter of approval and photos can be seen in the link below.

 [CTL01016](#)

Thanks,



Joshua Costa | Master Electrician

750 West Center St Suite 301 | West Bridgewater, MA 02379

Mobile: 508-967-5985

jcosta@clinellc.com | www.centerlinecommunications.com

Building a better network.

Smart design. Quality construction. Reliable maintenance.

Final Report of Special Inspections

Project: AT&T: CT1016 (FA:10034970) / ATC: 302485

Location: 134 Kikapoo Road, Middlefield, CT 06455-1334

Owner: Carrier: AT&T Mobility / Site: American Tower Corporation

Engineer of Record: Daniel P. Hamm, P.E.

Tower Engineering Professionals, LLC (TEP OPCO, LLC)

To the best of my information, knowledge and belief, the Special Inspections required by Chapter 17 for the project have been performed and all discovered discrepancies have been reported and resolved.

Representatives of TEP Northeast performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on June 19, 2023.

Based on my knowledge, information and belief the wireless installation substantially conforms to the approved plans, IBC 2015 with 2018 CT State Building Code Amendments, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-H), and the following:

1. Final Rev. 1 Construction Drawings dated 09/26/22, prepared by Hudson Design Group LLC, entitled "AT&T LTE 6C, 5G NR 1SR CBAND, 5G NR Activation, 5G NR Radio Amendment Plan."
2. Final Mount Analysis dated 09/14/22, prepared by Engineered Tower Solutions.

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications. This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation.

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,
Special Inspector

Daniel P. Hamm, P.E.
(Type or print name)



Signature

06/23/2023

Date





April 30, 2023 at 12:59:47 PM EDT
41.513670° N, 72.745872° W
91-199 Kickapoo Rd
Middlefield CT 06455



May 1, 2023 at 2:02:53 PM EDT
41.513608° N, 72.745827° W
91-199 Kickapoo Rd
Middlefield CT 06455





May 1, 2023 at 7:11:04 PM EDT
41.513628° N, 72.745880° W
91-199 Kickapoo Rd
Middlefield CT 06455