

From: Aja Chase <aja.chase@ericsson.com>
Sent: Wednesday, July 19, 2023 2:52 PM
To: CSC-DL Siting Council <Siting.Council@ct.gov>
Subject: EM-CING-083-200417

Good Afternoon CSC,

Please find the attached letter on the below site, as construction is now complete. If you need anything else, please reach out!

67 Fairchild Road	Middletown
-------------------	------------



Aja Chase
Construction Manager
AT&T NE Market
401-952-6205

Final Report of Special Inspections

Project: AT&T – LTE 5C_6C_5G NR_BWE 2020 upgrade – “Middletown Fairchild Road” – CT2547 (10141343)
Location: 50 Fairchild Road, Middletown, CT 06457
Owner: SBA Communications Group
Engineer of Record: Daniel P. Hamm, P.E.
Hudson Design Group, LLC.

To the best of my information, knowledge and belief, the Special Inspections required by Chapter 17 for the project have been performed and all discovered discrepancies have been reported and resolved.

Representatives of TEP Northeast performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on January 10, 2023.

Based on my knowledge, information and belief the wireless installation substantially conforms to the approved plans, IBC 2015 with 2018 CT State Building Code Amendments, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-H), and the following:

1. Final Rev3 Construction Drawings dated 04/10/2020, prepared by Hudson Design Group LLC, entitled “LTE 5C_6C_5G NR_BWE 2020 upgrade”
2. Final Mount Analysis dated 01-27-2020, prepared by Hudson Design Group LLC

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications. This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation.

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,
Special Inspector

Daniel P. Hamm, P.E.
(Type or print name)



Signature

01-17-2023

Date



Oct 11, 2020 at 9:22:17 AM
Middletown CT 06457
United States

