

Barbara Kassabian
750 West Center Street
Suite 301
West Bridgewater, MA 02379
bkassabian@clinellc.com
(603) 303-8001

August 8, 2023

Melanie A. Bachman
Acting Executive Director
Connecticut Siting Council
10 Franklin Square
New Britain, CT 06051

RE: EM-VER-096-200316 - Cellco Partnership d/b/a Verizon Wireless facility located off of Canterbury Road (a/k/a 4 Elkington Farm), New Milford, Connecticut.


Notice of Construction Complete

Dear Ms. Bachman:

The purpose of this letter is to notify the Siting Council that construction activity associated with the above-referenced facility modifications has been completed.

If you have any questions or need any additional information regarding this facility, please do not hesitate to contact me.

Sincerely,



Barbara Kassabian

Barbara Kassabian
c/o Cellco Partnership d/b/a Verizon Wireless
Centerline Communications, LLC
750 West Center Street, Suite 301
West Bridgewater, MA 02379
Mobile: (603) 303-8001
bkassabian@clinellc.com

Final Report of Special Inspections

Site Name: *New Milford CT*
Location Code: *467154*
Fuze Id: *15866217*
Project: *CBRS Add, RRH Upgrade*
Address: *4 Elkington Farm Road, New Milford, CT*
Owner: *Verizon Wireless*

Date: *August 3, 2023*

Engineer of Record: *Derek J. Creaser, P.E.*
Centerline Communications, LLC.

To the best of my information, knowledge and belief, the Special Inspections required for this project, and itemized in the *Statement of Special Inspections* submitted for permit, have been performed and all discovered discrepancies have been reported and resolved.

Representatives of Centerline Communications, LLC performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on July 18, 2023.

Based on my knowledge, information, and belief the Verizon Installation substantially conforms to the approved plans, IBC 2015, 2018 CT State Building Code, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-G), and the following:

1. Final Construction Drawings dated 01/28/20 by Tower Engineering Professionals.
2. Mount Analysis dated 01/17/20 by A.T. Engineering Service, PLLC.

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications.

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,
Special Inspector

Derek Creaser, P.E.
Director of A&E Services
dcreaser@clinellc.com

