

January 15, 2021

Attorney Melanie Bachman Acting Executive Director Connecticut Siting Council Ten Franklin Square New Britain, CT 06501

## EM-T-MOBILE-109-190722

T-Mobile Site ID CT11314C 1197 Norwich Road, Plainfield CT Notice of Compliance with Conditions and Construction Completion

## Dear Attorney Bachman:

The Connecticut Siting Council (Council) hereby acknowledges your notice to modify this existing telecommunications facility, pursuant to Section 16-50j-73 of the Regulations of Connecticut State Agencies with the following conditions:

- 1. Prior to T-Mobile's antenna installation, the antenna mount modifications shall be installed in accordance with the Mount Modification Report prepared by Paul J. Ford and Company, dated May 30, 2019 and stamped and signed by Justin T. Kline;
- 2. Within 45 days following the completion of equipment installation, T-Mo bile shall provide documentation t ha t its installation complied with the recommendation s of the Mount Modification Analysis;
- Prior to T-Mobile's antenna installation, the antenna mount modifications shall be installed in accordance with the Mount Modification Report prepared by Paul J. Ford and Company, dated Ma y 30, 201 9 and stamped and signed by Justin T. Kline;
- 4. Within 45 days following the completion of equipment installation, T-Mo bile s hall provide documentation that its installation complied with the recommendations of the Mount Modification Analysis;
- 5. Any deviation from the proposed modification as specified in this notice and supporting materials with the Council shall render this acknowledgement invalid;
- 6. Any material changes to this modification as proposed shall require the filing of a new notice with the Council;
- 7. Within 45 days after completion of construction, the Council s hall be notified in writing that construction has been completed;
- Any nonfunctioning antenna and associated antenna mounting equipment on this facility owned and operated by T-Mobile shall be removed within 60 days of t h e date the antenna ceased to function;
- 9. The validity of this action s hall expire one year from the date of this letter; and
- 10. The applicant may file a request for an extension of time beyond the one year deadline provided that such request is submitted to the Council not less than 60 days prior to the expiration.

The attached PE Closeout Letter dated December 1, 2020 provides evidence of compliance with the conditions outlined by the Council. In addition, T-Mobile hereby notifies the Council that construction of the acknowledged modifications were complete as of October 2, 2020.

Sincerely,

Victoria Masse

Victoria Masse Zoning and Permitting Northeast Site Solutions



Date: December 1, 2020

Craig Koppang Crown Castle 1220 Augusta Dr Suite 600, Houston, TX 77057	Paul J Ford and Company 250 E. Broad Street, Suite 600 Columbus, OH 43215 614.221.6679		
Subject:	Post-Modification Installation Inspection Desktop Review		
Carrier Designation:	<i>T-Mobil</i> e Equipment Change-ou Carrier Site Number: Carrier Site Name:	ıt	CT11314C Plainfield/I-395
Crown Castle Designation:	Crown Castle BU Number: Crown Castle Site Name: Crown Castle JDE Job Number Crown Castle Order Number:	:	826747 Plainfield/I-395 559247 479828 Rev. 7
Engineering Firm Designation:	Paul J Ford and Company Project Number:		A37519-1567.004.7101
Site Data:	1197 Norwich Rd, Plainfield, Windham County, CT 06234 Latitude 41.646325°, Longitude -71.941306°		
Structure Information:	Tower Height & Type: Mount Elevation: Mount Type:	150 Foot Monopole 149 Foot (1) 13.5 Foot Platform	
Dear Craig Koppang,	mount rype.	(1) 13.310	


*Paul J Ford and Company* is pleased to submit this "**Post-Modification Installation Inspection Desktop Review**" to confirm that the modifications have been completed in accordance with the conditional passing analysis by Paul J. Ford & Company dated 05/30/2019. PJF did not visit the site and was not present during the construction, this PMI desktop review is based on information provided by the contractor.

Based on our review of the close-out photos dated 09/29/2020, we have determined that the deviations in equipment installation are acceptable.

We at *Paul J. Ford and Company* appreciate the opportunity of providing our continuing professional services to you. If you have any questions or need further assistance on this or any other projects please give us a call.

Respectfully submitted by:

Ibrahim O. Huthman, E.I. MMD Structural Designer <u>IHuthman@pauljford.com</u>



<u>**Purpose**</u> – to verify that the modification installation is in accordance with the issued conditional passing analysis.

## Antenna and equipment placement and Geometry Certification:

- Per photos, the equipment on the mount is installed as depicted in Appendix A as included in the associated mount analysis.
- Per photos, the equipment on the mount is NOT installed as depicted in Appendix A as included in the associated mount analysis, though these deviations ARE structurally acceptable.
- Per photos, the equipment on the mount is not installed as depicted in Appendix A as included in the associated mount analysis, these deviations ARE NOT structurally acceptable.