

From: Josh Costa <jcosta@clinellc.com>
Sent: Tuesday, May 30, 2023 10:37 AM
To: CSC-DL Siting Council <Siting.Council@ct.gov>
Subject: 97 High St, Portland CSC site (EM-AT&T-113-220929) CTL01066

EXTERNAL EMAIL: This email originated from outside of the organization. Do not click any links or open any attachments unless you trust the sender and know the content is safe.

The work on site has been completed please see attached letter of engineer approval.

Below is the link to the photos.

 [CTL01066 FCCA Pics](#)

Thank you!



Joshua Costa | Master Electrician

750 West Center St Suite 301 | West Bridgewater, MA 02379

Mobile: 508-967-5985

jcosta@clinellc.com | www.centerlinecommunications.com

Building a better network.

Smart design. Quality construction. Reliable maintenance.

Final Report of Special Inspections

Project: CT1066 (10035005)

Location: 97 High Street, Portland, CT 06480

Owner: AT&T Mobility

Engineer of Record: Daniel P. Hamm, P.E.

Tower Engineering Professionals, LLC (TEP OPCO, LLC)

To the best of my information, knowledge and belief, the Special Inspections required by Chapter 17 for the project have been performed and all discovered discrepancies have been reported and resolved.

Representatives of TEP Northeast performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on May 11, 2023.

Based on my knowledge, information and belief the wireless installation substantially conforms to the approved plans, IBC 2021 with 2022 CT State Building Code Amendments, Structural Standards for Antenna Supporting Structures and Antennas (EIA/TIA-222-H), and the following:

1. Final Construction Drawings dated 11/23/2022, prepared by Hudson Design Group LLC, entitled "5G NR 1SR, LTE 5C, 4TXRX Software, 5G NR 1SR CBAND, 5G NR Activation, BBU Add, 5G NR Radio 2023 Upgrade."
2. Final Mount Structural Analysis dated 01-21-2022, prepared by Hudson Design Group LLC


All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications. This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation.

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,
Special Inspector

Daniel P. Hamm, P.E.

(Type or print name)



Signature

05-26-2023

Date

