

---

**From:** Aja Chase <aja.chase@ericsson.com>  
**Sent:** Tuesday, February 20, 2024 10:34 AM  
**To:** CSC-DL Siting Council  
**Subject:** EM-CING-116-220124  
**Attachments:** CT5482 - LTE 5C-6C - FSOSI - 2.8.24.pdf; 10071213.NYC-NJ\_Photos.240212.CTL05482.Post\_Construction\_Photos-Bulk.(Not\_specified).jpg

Good Morning CSC,

Please find attached FCCA letter and overall photo of work completed on the below site. Please let me know if you need anything else, thank you!

10071213	CTL05482	MRCTB052711	63 PUTNAM INDUSTRIAL PARK	PUTNAM	06260
----------	----------	-------------	---------------------------	--------	-------

Kindly,

Aja

## Final Report of Special Inspections

Project: AT&T: CT5482 (FA: 10071213) / SBA: CT00802 (FCC: 1202920)

Location: 63 Putnam Industrial Park, Putnam, CT 06260

Owner: Carrier: AT&T Mobility / Tower: SBA Communications

Engineer of Record: Daniel P. Hamm, P.E.

Tower Engineering Professionals, LLC (TEP OPCO, LLC)

To the best of my information, knowledge and belief, the Special Inspections required by Chapter 17 for the project have been performed and all discovered discrepancies have been reported and resolved.

Representatives of TEP Northeast performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on February 6, 2024.

Based on my knowledge, information and belief the wireless installation substantially conforms to the approved plans, IBC 2015 with 2018 CT State Building Code Amendments, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-H), and the following:

1. Final Rev. 0 Construction Drawings dated 12/28/2021, prepared by Hudson Design Group LLC, entitled "LTE 5C-6C UPGRADE."
2. Final Mount Analysis dated 05/03/2021, prepared by Hudson Design Group LLC.

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications. This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation.

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,  
Special Inspector


Daniel P. Hamm, P.E.



Signature

02/16/24

Date





Dec 22, 2023 12:39:33 PM  
3 Park Road  
Putnam  
Windham County  
Connecticut