

Final Report of Special Inspections

Date: April 3, 2024

Project: AT&T Wireless (5G/4XTRX/CBAND/ANT Mod/2022 Upgrade)

Site Id: CTL01855 FA Number: 10128094

Location: 320 Old Stagecoach Rd, Fairfield, CT

Owner: AT&T Wireless

Engineer of Record: Daniel Hamm, P.E.

Hudson Design Group, LLC.

To the best of my information, knowledge and belief, the Special Inspections required for this project, and itemized in the *Statement of Special Inspections* submitted for permit, have been performed and all discovered discrepancies have been reported and resolved.

Representatives of Centerline Engineering Svcs., PA performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on March 30, 2024.

Based on my knowledge, information, and belief the AT&T Installation substantially conforms to the approved plans, IBC 2018, 2022 CT State Building Code, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-H), and the following:

1. Final Construction Drawings dated 07/14/22, prepared by Hudson Design Group, LLC.

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications.

This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation. Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted, Special Inspector

Derek Creaser, P.E.
Director of A&E
Centerline Engineering Svcs., PA
dcreaser@clinellc.com

