

October 06, 2022

Melanie A. Bachman
Acting Executive Director
Connecticut Siting Council
10 Franklin Square
New Britain, CT 06051

RE: EM-CING-121-200501 Notice of Completion of Construction for New Cingular Wireless/ AT&T
Facility at 160 Witch Meadow Road, Salem, Connecticut

Dear Ms. Bachman:

The purpose of this letter is to notify you that construction activity associated with the above-referenced decision has been completed. The site was built to match the approved plans.

If you have any questions or need any additional information regarding this facility, please do not hesitate to contact me.

Sincerely,

Corey Michaud
Director of Project Management
Qualtek Wireless
16 Esquire Rd
Billerica, MA 01860



Final Report of Special Inspections

Project: CT2195 (FA 10035287)
Location: 160 Witch Meadow Road, Salem, CT 06420
Owner: AT&T
Engineer of Record: Daniel P. Hamm, P.E.
Hudson Design Group, LLC.

To the best of my information, knowledge and belief, the Special Inspections required by Chapter 17 for the project have been performed and all discovered discrepancies have been reported and resolved.

Representatives of Hudson Design Group LLC performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on July 28, 2020.

Based on my knowledge, information and belief the wireless installation substantially conforms to the approved plans, IBC 2015 with 2018 CT State Building Code Amendments, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-G), and the following:

1. Final Construction Drawings dated 04-29-2020, prepared by Hudson Design Group LLC, entitled "Salem North."
2. Final Mount Analysis dated 10-07-2019, prepared by Hudson Design Group LLC.
3. Final Structural Analysis dated 09-13-2019, prepared by Tower Engineering Solutions.

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications. This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation.

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,
Special Inspector

Daniel P. Hamm, P.E.

09-21-2020

Signature

Date

