



Barbara Kassabian 750 West Center Street Suite 301 West Bridgewater, MA 02379 bkassabian@clinellc.com (603) 303-8001

August 8, 2023

Melanie A. Bachman Acting Executive Director Connecticut Siting Council 10 Franklin Square New Britain, CT 06051

RE: EM-VER-126-200226 - Cellco Partnership d/b/a Verizon Wireless 0 Old Sheldon Rd (off Lane St) aka 15 Soundview Avenue, Shelton, Connecticut

Notice of Construction Complete

Dear Ms. Bachman:


The purpose of this letter is to notify the Siting Council that construction activity associated with the above-referenced facility modifications has been completed.

If you have any questions or need any additional information regarding this facility, please do not hesitate to contact me.

Sincerely,

Barbara Kassabian

Barbara Kassabian c/o Cellco Partnership d/b/a Verizon Wireless Centerline Communications, LLC 750 West Center Street, Suite 301 West Bridgewater, MA 02379 Mobile: (603) 303-8001 bkassabian@clinellc.com





Final Report of Special Inspections

Site Name: **Huntington CT** Date: August 8, 2023

468942 Location Code: Fuze Id: 15520665

Project: PCS/850 LTE/CBRS Carrier Add Address: 15 Soundview Avenue, Shelton, CT

Verizon Wireless Owner:

Engineer of Record: Derek J. Creaser, P.E.

Centerline Communications, LLC.

To the best of my information, knowledge and belief, the Special Inspections required for this project, and itemized in the Statement of Special Inspections submitted for permit, have been performed and all discovered discrepancies have been reported and resolved.

Representatives of Centerline Communications, LLC performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on July 18, 2023.

Based on my knowledge, information, and belief the Verizon Installation substantially conforms to the approved plans, IBC 2015, 2018 CT State Building Code, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-G), and the following:

- 1. Final Construction Drawings dated 12/02/19 by A.T. Engineering Service, PLLC.
- 2. Mount Analysis dated 12/04/19 by A.T. Engineering Service, PLLC.

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications.

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted, Special Inspector

Derek Creaser, P.E. Director of A&E Services dcreaser@clinellc.com

