



Barbara Kassabian  
750 West Center Street  
Suite 301  
West Bridgewater, MA 02379  
[bkassabian@clinellc.com](mailto:bkassabian@clinellc.com)  
(603) 303-8001

August 15, 2023

Melanie A. Bachman  
Acting Executive Director  
Connecticut Siting Council  
10 Franklin Square  
New Britain, CT 06051

**RE: TS-VER-131-191226** - Cellco Partnership d/b/a Verizon Wireless 80 Shuttle Meadow Road, Southington, Connecticut

**Notice of Construction Complete**

Dear Ms. Bachman:

The purpose of this letter is to notify the Siting Council that construction activity associated with the above-referenced facility modifications has been completed.

If you have any questions or need any additional information regarding this facility, please do not hesitate to contact me.

Sincerely,

A handwritten signature in black ink that reads "Barbara Kassabian".

Barbara Kassabian

Barbara Kassabian  
c/o Cellco Partnership d/b/a Verizon Wireless  
Centerline Communications, LLC  
750 West Center Street, Suite 301  
West Bridgewater, MA 02379  
Mobile: (603) 303-8001  
[bkassabian@clinellc.com](mailto:bkassabian@clinellc.com)

750 W Center St, Suite 301  
West Bridgewater, MA 02379  
781-713-4725

## Final Report of Special Inspections

**Site Name:** *Southington 3 CT* **Date:** *August 15, 2023*  
**Location Code:** *468851*  
**Fuze Id:** *2548199*  
**Project:** *LS6 Add, CBRS Add*  
**Address:** *80 Shuttle Meadow Rd, Southington, CT*  
**Owner:** *Verizon Wireless*

Engineer of Record: *Derek J. Creaser, P.E.*  
*Centerline Communications, LLC.*

To the best of my information, knowledge and belief, the Special Inspections required for this project, and itemized in the *Statement of Special Inspections* submitted for permit, have been performed and all discovered discrepancies have been reported and resolved.

Representatives of Centerline Communications, LLC performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on November 5, 2021.

Based on my knowledge, information, and belief the Verizon Installation substantially conforms to the approved plans, IBC 2015, 2018 CT State Building Code, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-G), and the following:

1. Final Construction Drawings dated 12/13/19 by A.T. Engineering Service, PLLC.
2. Antenna Mount Analysis dated 01/31/20 by A.T. Engineering Service, PLLC.

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications.

This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation.

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,  
Special Inspector

Derek Creaser, P.E.  
Director of A&E Services  
[dcreaser@clinellc.com](mailto:dcreaser@clinellc.com)

