

KENNETH C. BALDWIN

280 Trumbull Street Hartford, CT 06103-3597 Main (860) 275-8200 Fax (860) 275-8299 kbaldwin@rc.com Direct (860) 275-8345

Also admitted in Massachusetts and New York

June 13, 2024

Melanie A. Bachman, Esq. Executive Director/Staff Attorney Connecticut Siting Council 10 Franklin Square New Britain, CT 06051

Re: EM-VER-135-231018 – Cellco Partnership d/b/a Verizon Wireless Telecommunications Facility, 370 West Main Street, Stamford, Connecticut

Completion of Construction – Stamford West

Dear Attorney Bachman:

The purpose of this letter is to notify the Siting Council that construction activity associated with the above-referenced facility modification <u>has been completed</u>.

As required by the Council's approval, attached is a letter from Centerline Communications dated May 20, 2024, verifying that the facility modifications were completed in accordance with the August 14, 2023, Mount Analysis Report prepared by Colliers Engineering and Design. Photographs of the completed improvements are also attached.

If you have any questions or need any additional information regarding this facility, please do not hesitate to contact me.

Sincerely,

Kenneth C. Baldwin

Attachment Copy to:

Aleksey Tyurin

29822876-v1



Final Report of Special Inspections

Site Name: Stamford W CT Date: May 20, 2024

Location Code: 468191
Fuze Id: 17226475
Project: RF Filter Add

Address: 370 West Main Street, Stamford, CT

Owner: Verizon Wireless

Engineer of Record: Derek J. Creaser, P.E.

Centerline Communications, LLC.

To the best of my information, knowledge and belief, the Special Inspections required for this project, and itemized in the *Statement of Special Inspections* submitted for permit, have been performed and all discovered discrepancies have been reported and resolved.

Representatives of Centerline performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on May 14, 2024.

Based on my knowledge, information and belief, the Verizon Installation substantially conforms to the approved plans, IBC 2021, 2022 CT State Building Code, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-H), and the following:

- 1. Final Construction Drawings dated 09/12/23 by Centerline Communications.
- 2. As-Built Redlined Construction Drawings dated 10/20/24 by NEC Group, LLC.
- 3. Antenna Mount Analysis dated 08/14/23 by Colliers Engineering.

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications. This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation.

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted, Special Inspector

Derek Creaser, P.E. Director of A&E Services dcreaser@clinellc.com



