

From: Lord, Andrew <andrew.lord@eversource.com>
Sent: Monday, June 14, 2021 3:03 PM
To: CSC-DL Siting Council <Siting.Council@ct.gov>
Cc: Shanley, Kathleen M <kathleen.shanley@eversource.com>
Subject: EM-EVER-136-210128 - CT Voice Radio (Sterling) - Statement of Special Inspection

Please see the attached Notice of Completion of Construction – Statement of Special Inspection for the above-referenced project. Please contact me if you have any questions.

Andrew Lord
Project Siting Specialist
56 Prospect Street
Hartford, CT 06103
860 728-4651

This electronic message contains information from Eversource Energy or its affiliates that may be confidential, proprietary or otherwise protected from disclosure. The information is intended to be used solely by the recipient(s) named. Any views or opinions expressed in this message are not necessarily those of Eversource Energy or its affiliates. Any disclosure, copying or distribution of this message or the taking of any action based on its contents, other than by the intended recipient for its intended purpose, is strictly prohibited. If you have received this e-mail in error, please notify the sender immediately and delete it from your system. Email transmission cannot be guaranteed to be error-free or secure or free from viruses, and Eversource Energy disclaims all liability for any resulting damage, errors, or omissions.

Final Report of Special Inspections

Project: *CSP # 49 Sterling*
AECOM Detailed Structural Analysis and Modifications of and Existing 140' Self Supporting Lattice Tower and Foundation for Proposed Antenna Arrangement, AECOM Project 60627154 / EVS-011 (b2) Rev. 1, ES-056, Dated November 25, 2020

Location: *389 Ekonk Hill Road, Sterling, CT*

Owner: *Connecticut State Police*

Owner's Address: *1111 Country Club Road, Middletown, CT 06457*

Architect of Record: *NA*

Structural Engineer of Record: *Richard A. Sambor, P.E.*

To the best of my information, knowledge and belief, the Special Inspections required for this project, and itemized in the *Statement of Special Inspections* submitted for permit, have been performed and all discovered discrepancies have been reported and resolved other than the following:

Comments: *None*

(Attach continuation sheets if required to complete the description of corrections.)

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,
Special Inspector

Richard A. Sambor, P.E.

(Type or print name)

Richard A. Sambor

Signature

6/11/21

Date

