

From: [Tatasciore, Domenica](#)
To: [CSC-DL Siting Council](#)
Cc: [Fontaine, Lisa](#)
Subject: EM-VER-144-220114 - 425 Indian Ledge Park Rd, Trumbull, CT - 881535_552698
Date: Friday, August 11, 2023 1:36:47 PM
Attachments: [EM-VER-144-220114 - 425 Indian Ledge Park Rd, Trumbull, CT - 881535_552698.pdf](#)
[Engineering Letter.pdf](#)

Hello,

This email is to confirm the Verizon installation has been completed.
Please let me know if you have any questions

Thanks,

DOMENICA TATASCIORE
Site Acquisition Specialist
T: 508-621-9161

CROWN CASTLE
1800 West Park Drive, Westborough, MA 01581
CrownCastle.com

This email may contain confidential or privileged material. Use or disclosure of it by anyone other than the recipient is unauthorized. If you are not an intended recipient, please delete this email.

Final Report of Special Inspections

Project: *Crown 881535/App 552698/Verizon Wireless*
Location: *425 Indian Ledge Park Rd, Trumbull, CT 06611*
Tower Owner: *Crown Castle*
Carrier: *Verizon Wireless*

Engineer of Record: *Scott C. Brantley, P.E.*
Tower Engineering Professionals (TEP)

To the best of my information, knowledge and belief, the Special Inspections required by Chapter 17 for the project have been performed and all discovered discrepancies have been reported and resolved.

Representatives of TEP performed the Visual Final Inspection after the construction/amendment of the existing Verizon Wireless facility at the above-referenced address. The Final Inspection was performed on June 26, 2023.


Based on my knowledge, information and belief the wireless installation substantially conforms to the approved plans, IBC 2015 with 2018 CT State Building Code Amendments, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-G), and the following:

1. Final Construction Drawings dated 01-07-2022, Rev 0), prepared by TEP."
2. Final Structural Analysis dated 07-07-2021, prepared by TEP.
3. Final Mount Analysis dated 11-19-2021, prepared by Maser Consulting.
4. As-Built Drawings dated 06-23-23 prepared by Neil Coon.
5. Post-Construction Photos dated 02/02/23, prepared by the Contractor.

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications. This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,
Special Inspector

Scott C. Brantley, P.E.
(Type or print name)


Signature

06/27/2023
Date



DIRECTION
67 deg(T)

41.27314°N
073.21358°W

ACCURACY 4 m
DATUM WGS84



Taken With
Context Camera

2023-04-28
16:16:44-04:00

GPS: 41.273139, -73.213578

04/28/2023 16:16:44