

From: Aja Chase <aja.chase@ericsson.com>
Sent: Friday, February 2, 2024 3:00 PM
To: CSC-DL Siting Council <Siting.Council@ct.gov>
Subject: EM-ATT-146-230515

Good Afternoon CSC,


Please find FCCA and photo of completed work attached on the below sites. Please reach out if you have any questions!

10071294	CTL05328	MRCTB056005	777 TALCOTTVILLE ROAD ROCKVILLE	VERNON	06066
----------	----------	-------------	---------------------------------	--------	-------

Kindly,

Aja

January 3, 2024
779 Talcottville Rd
Vernon Rockville CT 06066
United States



Final Report of Special Inspections

Project: AT&T: CTL05328 (FA: 10071294) / ATC: 302529)

Location: 777 Talcottville Road, Vernon, CT 06066

Owner: Carrier: AT&T Mobility / Tower: American Tower Corporation

Engineer of Record: Daniel P. Hamm, P.E.

Tower Engineering Professionals, LLC (TEP OPCO, LLC)

To the best of my information, knowledge and belief, the Special Inspections required by Chapter 17 for the project have been performed and all discovered discrepancies have been reported and resolved.

Representatives of TEP Northeast performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on January 22, 2024.

Based on my knowledge, information and belief the wireless installation substantially conforms to the approved plans, IBC 2021 with 2022 CT State Building Code Amendments, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-H), and the following:

1. Final Rev. 4 Construction Drawings dated 06/14/2023, prepared by TEP Northeast (TEP OPCO, LLC), entitled "4TX4RX SOFTWARE RETROFIT, 5G NR 1SR CBAND, 5G NR RADIO, 5G NR 1DR-1", 2023 UPGRADE."
2. Final Rev. 1 Mount Analysis dated 03/20/2023, prepared by TEP Northeast (TEP OPCO, LLC).

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications. This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation.

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,
Special Inspector


Daniel P. Hamm, P.E.

A handwritten signature in blue ink, appearing to read "D. Hamm", is written over a horizontal line.

Signature

01/25/2024

Date



Licensed Professional
Seal