

**From:** Aja Chase <aja.chase@ericsson.com>  
**Sent:** Wednesday, August 21, 2024 8:43 AM  
**To:** CSC-DL Siting Council <Siting.Council@ct.gov>  
**Subject:** EM-CING-151-220808

Good Afternoon CSC,

This site is completed and the FCCA and photo of overall work completed is attached. Please let us know if you need any additional information.

10035415	CTL01125	MRCTB056108	EM-CING-151-220808
----------	----------	-------------	--------------------

Thanks,

Aja

# Final Report of Special Inspections

**Project:** CTL01125 (10035415)

**Location** 299 SHEFFIELD STREET. WATERBURY, CT 06704

**Owner:** AT&T

**Engineer of Record:** Daniel P. Hamm, P.E.  
Tower Engineering Professionals, LLC (TEP OPCO, LLC)

To the best of my information, knowledge and belief, the Special Inspections required by Chapter 17 for the project have been performed and all discovered discrepancies have been reported and resolved.

Representatives of TEP Northeast performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on 5/1/2024.

Based on my knowledge, information and belief the wireless installation substantially conforms to the approved plans, IBC 2015 with 2018 CT State Building Code Amendments, Structural Standards for Antenna Supporting Structures and Antennas (EIA/TIA-222-H), and the following:

1. Final Construction Drawings dated 6/3/2022 prepared by Hudson Design Group LLC (TEP OPCO, LLC) entitled "5G NR 1SR CBAND Antenna Modifications"
2. Final Mount Analysis dated 05-06-2022, prepared by Hudson Design Group LLC, (TEP OPCO, LLC)

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications. This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation.

Respectfully submitted,  
Special Inspector

Daniel P. Hamm, P.E.  
(Type or print name)



Signature

08/20/24

Date



DIRECTION  
26 deg(T)

41.59388°N  
073.05083°W

ACCURACY 3 m  
DATUM WGS84



2024-01-12  
16:00:10-05:00