From: Josh Costa <jcosta@clinellc.com> Sent: Friday, May 19, 2023 10:21 AM

To: CSC-DL Siting Council <Siting.Council@ct.gov>

Subject: 515 post rd E, Westport - CSC Site: EM-CING-158-220513 - CTL02153

The work on site has been completed please see attached letter of engineer approval.

Below is the link to the photos.



Thanks,



Joshua Costa | Master Electrician

750 West Center St Suite 301 | West Bridgewater, MA 02379

Mobile: 508-967-5985

<u>Jcosta@clinellc.com|</u> <u>www.centerlinecommunications.com</u>

Building a better network.

Smart design. Quality construction. Reliable maintenance.



Final Report of Special Inspections

Project: CT2153 (10035241)

Location: 515 Boston Post Road East, Westport, CT 06880

Owner: AT&T Mobility

Engineer of Record: Daniel P. Hamm, P.E.

Tower Engineering Professionals, LLC (TEP OPCO, LLC)

To the best of my information, knowledge and belief, the Special Inspections required by Chapter 17 for the project have been performed and all discovered discrepancies have been reported and resolved.

Representatives of TEP Northeast performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on May 2, 2023.

Based on my knowledge, information and belief the wireless installation substantially conforms to the approved plans, IBC 2015 with 2018 CT State Building Code Amendments, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-H), and the following:

- 1. Final Construction Drawings dated 09/15/2022, prepared by Hudson Design Group LLC, entitled "5G NR Radio II 5G NR 1SR CBAND Upgrade."
- 2. Final Rev. 1 Mount Analysis dated 03-24-2022, prepared by Hudson Design Group LLC
- 3. Final Structural Analysis dated 12-10-2021, prepared by Hudson Design Group LLC.

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications. This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation.

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted, Special Inspector		OF CONNECTION OF
Daniel P. Hamm, P.E. (Type or print name)		*
	05-10-2023	SSIONAL ENGINEERS
Signature	Date	Licensed Professional



Register for an Account Reports (2) ▼ Login

Get help at Westport Online Services Portal Information Hub

Search...

Home Building Planning Dog Licenses Health Conservation Public Works More •

Search Applications

Record BLD-2022-02869: **Commercial Miscellaneous Record Status: Closed**

Record Info ▼

Payments >

Work Location

515 E POST RD *

Record Details

Applicant:

NEXIUS SOLUTIONS INC NEXIUS SOLUTIONS INC Phone 2:6175940212 legal@nexius.com

Project Description:

ON BEHALF OF AT&T - REMOVE 3 ANTENNAS, INSTALL 9 ANTENNAS, 1 SURGE ARRESTOR, 2 DC CABLE AND 1 PLATFORM

515 POST RD E - MISC. - C

MOUNT ON THE EXISTING MONOPOLE.

Licensed Professional:

CENTERLINE COMMUNICATIONS LLC jyork@clinellc.com CENTERLINE COMMUNICATIONS LLC 750 W CENTER ST STE 301 WEST BRIDGEWATER, MA, 023791545 Home Phone: 7818311985 MAJOR CONTRACTOR MCO.0902831

Owner:

WESTPORT TOWN OF * 110 MYRTLE AVE **WESTPORT CT 6880**

▶ More Details

©2022 Town of Westport, CT. All Rights Reserved. | 110 Myrtle Ave. Westport, CT 06880 | Phone (203) 341-1000