

From: Aja Chase <aja.chase@ericsson.com>
Sent: Thursday, April 4, 2024 1:05 PM
To: CSC-DL Siting Council <Siting.Council@ct.gov>
Subject: EM-CING-165-220822

Good Afternoon CSC,

Please see FCCA and photo of work completed on the above site, as work is now completed.

Thanks,

Aja

Final Report of Special Inspections

Project: CTL05270 (FA: 10071333)

Location: 2 Volunteer Drive, Windsor Locks, CT 06096

Owner: AT&T Mobility

Engineer of Record: Daniel P. Hamm, P.E.
Tower Engineering Professionals, LLC (TEP OPCO, LLC)

To the best of my information, knowledge and belief, the Special Inspections required by Chapter 17 for the project have been performed and all discovered discrepancies have been reported and resolved.

Representatives of TEP Northeast performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on month day, year.

Based on my knowledge, information and belief the wireless installation substantially conforms to the approved plans, IBC 2015 with 2018 CT State Building Code Amendments, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-H), and the following:


1. Final Rev. 1 Construction Drawings dated 09/15/2022, prepared by Hudson Design Group LLC, entitled "5G NR ACTIVATION, 5G NR RADIO, 5G NR 1SR CBAND, BBU ADD, 5G NR 1SR."
2. Final Mount Analysis dated 03/08/2024, prepared by Tower Engineering Professionals.

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications. This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation.

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,
Special Inspector

Daniel P. Hamm, P.E.
(Type or print name)



Signature

03/14/2024

Date



Jan 18, 2024 at 3:32:11 PM
4-34 Volunteer Dr
Windsor Locks CT 06096
United States

