

Mulnite Farms

East Windsor, Connecticut

Photo Location Figure

Source: VHB, CTDEEP, USGS, ArcGIS Online




Photo 1 Barber Hill Road Site Entrance





Photo 2 Staging Area



\\vhb\gbl\proj\Wethersfield\42518.01\Correspondence\Interrogatories\CSC Set 1\Photo Exhibit.dwg




Photo 3 Southwest Site Corner Looking North



 $\verb|\whb\gbl\proj\Wethersfield\42518.01\Correspondence\Interrogatories\CSC\ Set\ 1\Photo\ Exhibit.dwg$




Photo 4 Existing Site Road Looking East






Photo 5 Northwest Site Corner looking East






Photo 6 Stormwater Basin #1






Photo 7 Stormwater Basin #2






Photo 8 Northeast Site Corner Looking West





Photo 9 Stormwater Basin #3






Photo 10 Southeast Site Corner Looking North

