

56 Prospect Street P.O. Box 270 Hartford, CT 06141-0270

Kathleen M. Shanley Manager – Transmission Siting Tel: 860-728-4527

June 7, 2021

Ms. Melanie Bachman, Executive Director Connecticut Siting Council Ten Franklin Square New Britain, CT 06051

RE: Petition No. 1429: 1768 Lattice Tower Replacement Project

Monthly Construction Progress Report - May 2021

Dear Ms. Bachman:

Pursuant to the Regulations of Connecticut State Agencies Section 16-50j-62(b)(3) and as described in the *Partial Development and Management Plan for the 1768 Lattice Tower Replacement Project*, dated January 2021, The Connecticut Light and Power Company doing business as Eversource Energy (Eversource) hereby provides to the Connecticut Siting Council ("Council") this Construction Progress Report for the month of May 2021.

Should you or other Council members have any questions regarding this submission, please do not hesitate to contact me via e-mail at kathleen.shanley@eversource.com or telephone at (860) 728-4527.

Sincerely

Kathleen M. Shanley

Enclosure

PETITION NO. 1429 1768 LATTICE TOWER REPLACEMENT PROJECT MONTHLY CONSTRUCTION PROGRESS REPORT MAY 2021

1. LATTICE TOWER REPLACEMENTS AND TRANSMISSION LINE MODIFICATIONS

During May, crews erected new structures, removed existing structures, continued overhead electrical work, began removing temporary construction matting and initiated restoration activities.

Eversource also continued to perform routine inspections to verify the integrity of erosion and sedimentation controls and to monitor work in or adjacent to sensitive natural resource areas.

2. MINOR DEVELOPMENT & MANAGMENT (D&M) PLAN CHANGES

The work performed in May did not require any changes or deviations from the approved Partial Development and Management Plan.

3. **ACTIVITY SUMMARY TABLE**

ROW Vegetation Management (% Complete)	Access Roads/ Work Pads (% Complete)	Foundation Installation: # of Foundations/# Installed (% Complete)	Structure Installation: # Structures/#Install ed (% Complete)	Wire Stringing (% Complete)	Structure Removal (% Complete)	Restoration (% Complete)
100%	100%	8/8; 100%	68/68; 100%	80%% (Conductor) 61% (OPGW)	100%	42%