Silicon Ranch - Litchfield/Torrington Quantitative and Qualitative Visual Impacts




Figure 1 - Viewshed from residential property at 1167 Highland Avenue




Figure 2 - Viewshed from Town Farm Road




Figure 3 - Viewshed from Town Farm Road




Figure 4 - Viewshed from Wilson Road/Town Farm Road Intersection




Figure 5 - Viewshed from residential property on Wimbeldon Court




Figure 6 - Observation Point Location Map




Figure 7 - OP 1 Existing Conditions



Figure 8 - OP 1 Proposed Conditions




Figure 9 - OP 2 Existing Conditions




Figure 10 - OP-2 Proposed Conditions




Figure 11 - OP 3 Existing Conditions




Figure 12 - OP 3 Proposed Conditions




Figure 13 - OP 4 Existing Conditions




Figure 14 - OP 4 Proposed Conditions