





View from 10 Rockville Road



Visual Impact Study 1
Photovoltaic Installation
Mulnite Farm - East Windsor, Connecticut

Source:
 Prepared for:
 Date: July 2021






Visual Impact Study 2

Photovoltaic Installation



Mulnrite Farm - East Windsor, Connecticut

Source:
Prepared for:
Date: July 2021





View from Residence at 37 Miller Road





Visual Impact Study 3

Photovoltaic Installation


Mulnite Farm - East Windsor, Connecticut

Source:
Prepared for:
Date: July 2021





View from Residence at 41 Miller Road



Visual Impact Study 4

Photovoltaic Installation

Mulnite Farm - East Windsor, Connecticut

Source:
Prepared for:
Date: July 2021

