

**From:** [Karin Turner](#)  
**To:** [CSC-DL Siting Council](#)  
**Cc:** [Evan Thibodeau](#); [NE Permitting](#)  
**Subject:** PETITION NO. 1476 - 2627 Day Hill Road, Bloomfield, CT - CT3387/NSB  
**Date:** Friday, September 29, 2023 11:58:18 AM  
**Attachments:** [image001.png](#)  
[CT3387\\_FSSI\\_08.30.2023.pdf](#)

---

EXTERNAL EMAIL: This email originated from outside of the organization. Do not click any links or open any attachments unless you trust the sender and know the content is safe.

Good afternoon,

The AT&T modifications on the existing telecommunications facilities at the subject site are complete and we are looking to close the CSC Permit. Attached are site photos and the FSSI.

Should you require any additional information, please let us know.

Thank you.

Karin

**Karin L. Turner** / Construction Operations Specialist / 978.437.0443 /  
[kturner@qualtekwireless.com](mailto:kturner@qualtekwireless.com)  
11 Northeastern Blvd, Suite 102, Nashua, NH 03062



Disclaimer: This email is intended only for the use of the individual or entity to which it is addressed, and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If you received this communication in error, please do not distribute it and notify us immediately by email ([administrator@qualtekservices.com](mailto:administrator@qualtekservices.com)) or via telephone (484.804.4500) and delete the original message. Unless expressly stated in this email, nothing in this message or any attachment should be construed as a digital or electronic signature.

## Final Report of Special Inspections

Project: CT3387 (NSB)

Location: 2627 Day Hill Road Bloomfield, CT 06002

Owner: AT&T Mobility

Engineer of Record: Daniel P. Hamm, P.E.

Tower Engineering Professionals, LLC (TEP OPCO, LLC)

To the best of my information, knowledge and belief, the Special Inspections required by Chapter 17 for the project have been performed and all discovered discrepancies have been reported and resolved.

Representatives of TEP Northeast performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on August 9, 2023.

Based on my knowledge, information and belief the wireless installation substantially conforms to the approved plans, IBC 2015 with 2018 CT State Building Code Amendments, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-H), and the following:

1. Final Construction Drawings dated 09/26/2022, prepared by Hudson Design Group LLC, entitled "NSB".
2. Final Mount Analysis dated 04/21/2021, prepared by Hudson Design Group LLC.
3. Final Structural Analysis dated 09/10/2021, prepared by American Tower Corporation.


All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications. This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation.

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,  
Special Inspector

Daniel P. Hamm, P.E.

(Type or print name)

A handwritten signature in blue ink, appearing to read 'D. Hamm', written over a horizontal line.

Signature

08/30/2023

Date





5.24.2023 08:25



5.24.2023 08:25