

A Photo Location and Direction Taken

4308 Photo ID

Limit of Solar Array

Subject Property Boundary

<u>Note:</u> The aerial photo was acquired through the Esri Imagery Web Service. Aerial photography dated 2023.

DISCLAIMER: Verdantas LLC has furnished this map to the Client for its sole and exclusive use as a preliminary planning and screening tool. This map is reproduced from geospatial information compiled from third-party sources which may change over time and are not accurate as to mapping, surveying or engineering standards. Verdantas LLC makes no representation or warranty as to the content, accuracy, timeliness or completeness of any information. In no event will Verdantas LLC, its owners, officers employees or agents, be liable for damages of any kind arising out of the use of this map by Client or any other party.

verdantas

16 Soundview Drive Woodbridge, CT 06525

Photo Log

Soundview Solar Facility Greenskies Clean Energy

1 in = 130 f

Site Photographs

 Project No.
 24412
 Address
 16 Soundview Dr, Woodbridge, CT, 06525, USA

 Project Name
 Soundview Solar
 Report
 Field Inspection



Photo ID: 4248 Image Direction: view south

Image Direction: view south

Notes: Existing Property Owner Driveway

Date Taken: August 15, 2024 9:08 AM

Latitude: 41.36824167 **Longitude:** -73.011475



Image Direction: view north Latitude: 41.36825556 Longitude: -73.01149722 Notes: Existing Property Owner Driveway

Site Photographs

Project No. 24412 Address 16 Soundview Dr, Woodbridge, CT, 06525, USA
Project Name Soundview Solar Report Field Inspection



Photo ID: 4251 **Date Taken:** August 15, 2024 9:32 AM

Image Direction: view west Latitude: 41.36824722 Longitude: -73.01100833 Notes: View of Western Most Edge of proposed Solar Array and approximated location of Proposed

Stormwater Management System



Photo ID: 4253 **Date Taken:** August 15, 2024 9:33 AM

Image Direction: view west Latitude: 41.36763889 Longitude: -73.01101667

Notes: View of Interior Wooded Area of Proposed Solar Array

Site Photographs

Project No. 24412 Address 16 Soundview Dr, Woodbridge, CT, 06525, USA
Project Name Soundview Solar Report Field Inspection



Photo ID: 4254 **Date Taken:** August 15, 2024 9:35 AM

Image Direction: view south Latitude: 41.36758056 Longitude: -73.01126111

Notes: View of Southern Edge of Treeline adjacent to Property Line



Photo ID: 4255 **Date Taken:** August 15, 2024 9:35 AM

Image Direction: view east Latitude: 41.36752222 Longitude: -73.01123889

Notes: View of Proposed Solar Array Development

Site Photographs

Project No. 24412 Address 16 Soundview Dr, Woodbridge, CT, 06525, USA
Project Name Soundview Solar Report Field Inspection



Photo ID: 4256 Date Taken: August 15, 2024 9:41 AM Latitude: Longitude:

Notes: View of Centrally located Maintained Grass Pathway



Photo ID: 4257 Date Taken: August 15, 2024 9:43 AM Image Direction: view south Latitude: 41.36713889 Longitude: -73.01305278

Notes: View of the Existing Barn to be demolished as part of the Proposed Solar Development

Site Photographs

Project No. 16 Soundview Dr, Woodbridge, CT, 06525, USA 24412 Address Project Name Report Soundview Solar Field Inspection



Date Taken: August 15, 2024 9:46 AM **Photo ID: 4260** Latitude: 41.36640278 Image Direction: view west Longitude: -73.01296111 Notes: View of Centrally located Wooded Vegetation to be Cleared as part of Solar Development



Photo ID: 4261 Date Taken: August 15, 2024 9:46 AM Latitude: 41.36640278

Image Direction: view south Longitude: -73.01296111

Notes: View of Centrally located Wooded Vegetation with Grass Pathway

Site Photographs

Project No. 24412 Address 16 Soundview Dr, Woodbridge, CT, 06525, USA
Project Name Soundview Solar Report Field Inspection



Image Direction: view southeast Latitude: 41.36641667 Longitude: -73.01296111

Notes: View of Centrally located Wooded Vegetation with Grass Pathway



Photo ID: 4263 Date Taken: August 15, 2024 9:48 AM

Image Direction: view southeast Latitude: 41.36738333 Longitude: -73.01180278

Notes: Overall View of Proposed Solar Array location

Site Photographs

Project No. 24412 Address 16 Soundview Dr, Woodbridge, CT, 06525, USA
Project Name Soundview Solar Report Field Inspection



Image Direction: view northeast Latitude: 41.36661944 Longitude: -73.01304722

Notes: View of Existing Stonewall to be Removed (Deemed Culturally Insignificant)



Photo ID: 4265

Date Taken: August 15, 2024 9:52 AM

Image Direction: view porthogst

Latitude: 41 36721667

Latitude: 41 36721667

Image Direction: view northeast Latitude: 41.36721667 Longitude: -73.01331389

Notes: View of Existing Stonewall to be Removed (Deemed Culturally Insignificant)

Site Photographs

Project No. 24412 Address 16 Soundview Dr, Woodbridge, CT, 06525, USA
Project Name Soundview Solar Report Field Inspection



Photo ID: 4266 Date Taken: August 15, 2024 9:56 AM Image Direction: view northeast Latitude: 41.36871667 Longitude

Image Direction: view northeast Latitude: 41.36871667 Longitude: -73.01306111

Notes: View of Existing Transformer to the North of Existing Gravel Driveway and adjacent Property Line



Photo ID: 4268 **Date Taken:** August 15, 2024 9:57 AM

Image Direction: view west **Latitude:** 41.36808333 **Longitude:** -73.01318333 **Notes:** View of Centrally located Wooded Vegetation to be Cleared as part of Solar Development



Site Photographs

Project No. 24412 Address 16 Soundview Dr, Woodbridge, CT, 06525, USA
Project Name Soundview Solar Report Field Inspection



Photo ID: 4270 Image Direction: view north

Notes: Existing Property Owner Driveway

Date Taken: August 15, 2024 9:59 AM

Latitude: 41.36780556 **Longitude:** -73.01493889



Photo ID: 4271 Image Direction: view south **Date Taken:** August 15, 2024 9:46 AM **Latitude:** 41.36640278 **Longitude:** -73.01296111

Notes: View of Western Wooded Vegetation to be Cleared as part of Solar Development

Site Photographs

Project No. 24412 Address 16 Soundview Dr, Woodbridge, CT, 06525, USA
Project Name Soundview Solar Report Field Inspection



Photo ID: 4272 Date Taken: August 15, 2024 10:00 AM Latitude: 41.36766111 Longitude: -73.01545

Notes: View of Western Wooded Vegetation to be Cleared as part of Solar Development



Photo ID: 4273 Image Direction: view northwest Notes: Existing Property Owner Driveway **Date Taken:** August 15, 2024 10:01 AM

Latitude: 41.36769167 **Longitude:** -73.01610556

Site Photographs

Project No. 24412 Address _____ 16 Soundview Dr, Woodbridge, CT, 06525, USA Project Name Report Soundview Solar Field Inspection



Photo ID: 4274 Image Direction: view north

Date Taken: August 15, 2024 10:02 AM

Latitude: 41.36811111

Longitude: -73.01664722



Photo ID: 4275 Date Taken: August 15, 2024 10:02 AM

Image Direction: view northeast **Latitude:** 41.36811111 **Longitude:** -73.01664722 Notes: View of Existing Transformer to the North of Existing Gravel Driveway and adjacent Property Line

Site Photographs

Project No. 24412 Address 16 Soundview Dr, Woodbridge, CT, 06525, USA
Project Name Soundview Solar Report Field Inspection



Photo ID: 4276

Image Direction: view west

Latitude: 41.36781944

Notes: View of Centrally located Wooded Vegetation to be Cleared as part of Solar Development



Photo ID: 4277 Date Taken: August 15, 2024 10:03 AM Image Direction: view south Latitude: 41.368075 Longitude: -73.01666389 Notes: View of Centrally located Wooded Vegetation to be Cleared as part of Solar Development

Site Photographs

Project No. 24412 Address _____ 16 Soundview Dr, Woodbridge, CT, 06525, USA Project Name Soundview Solar Report Field Inspection



Photo ID: 4279

Date Taken: August 15, 2024 10:09 AM **Latitude:** 41.368575 **Longitude** Longitude: -73.01213056 Image Direction: view southwest

Notes: View of Proposed Solar Array Development

Site Photographs

 Project No.
 24412
 Address
 16 Soundview Dr, Woodbridge, CT, 06525, USA

 Project Name
 Soundview Solar
 Report
 Field Inspection



Photo ID: 4297 **Date Taken:** August 15, 2024 9:37 AM

Image Direction: view northwest Latitude: 41.36818611 Longitude: -73.01158889

Notes: View of Proposed Fence Line Alignment




Image Direction: view west Latitude: 41.36811944 Longitude: -73.01231389

Notes: View of existing vegetation

Site Photographs

Project No. 24412 Address 16 Soundview Dr, Woodbridge, CT, 06525, USA
Project Name Soundview Solar Report Field Inspection



Image Direction: view southwest Latitude: 41.368 Longitude: -73.01340556

Notes: View of Shed to be demolished as part of the Proposed Solar Development



Photo ID: 4303 Image Direction: view east Notes: View of interior vegetation **Date Taken:** August 15, 2024 9:52 AM

Latitude: 41.36540556 **Longitude:** -73.01506111

Site Photographs

Project No. 24412 Address 16 Soundview Dr, Woodbridge, CT, 06525, USA
Project Name Soundview Solar Report Field Inspection



Photo ID: 4305 Image Direction: view northwest Notes: View of interior vegetation **Date Taken:** August 15, 2024 9:58 AM

Latitude: 41.36695 **Longitude:** -73.01329722



Photo ID: 4308 **Date Taken:** August 15, 2024 10:07 AM

Image Direction: view north Latitude: 41.36841667 Longitude: -73.01133611

Notes: View of Existing Curb Cut at Termination of Soundview Drive Cul-de-Sac