



- Approximate Location of Photos
- Subject Property Boundary

Notes: The aerial photo was acquired through the Esri Imagery Web Service. Aerial photography dated 2023.

Parcel data was acquired through CTGIS.

DISCLAIMER: Verdantas LLC has furnished this map to the Client for its sole and exclusive use as a preliminary planning and screening tool. This map is reproduced from geospatial information compiled from third-party sources which may change over time and are not accurate as to mapping, surveying or engineering standards. Verdantas LLC makes no representation or warranty as to the content, accuracy, timeliness or completeness of any information. In no event will Verdantas LLC, its owners, officers, employees or agents, be liable for damages of any kind arising out of the use of this map by Client or any other party.




Old Maids Lane
Woodbridge, CT 06525

Photo Log

Soundview Solar Facility
Greenskies Clean Energy

Project Number	24412
Date	02/2026
Author	bsanchez
Scale	1 in = 250 ft
Figure	1



Edited: 2/22/2026 File Location: C:\Users\bsanchez\OneDrive - Verdantas\GIS Hub - Files\Project Files\04412\Greenskies\04412 - Connecticut Solar Design and Permitting\04412_06_PhotoLog.aprx Layout: 24412_Fig01_OldMaidsPhoto

Project No. 24412 Address Old Maids Ln, Glastonbury, CT, 06073, USA
Project Name Old Maids Lane Report Project Area Photographs



Photo ID: IMG_0485 **Date Taken:**
Image Direction: view southeast **Latitude:** 41.63181611 **Longitude:** -72.61861547
Notes: View of existing manmade wetland pond



Photo ID: IMG_0486 **Date Taken:**
Image Direction: view southwest **Latitude:** 41.63192809 **Longitude:** -72.61828233
Notes: View of existing manmade wetland pond

Project No. 24412 Address Old Maids Ln, Glastonbury, CT, 06073, USA
Project Name Old Maids Lane Report Project Area Photographs



Photo ID: IMG_3960 **Date Taken:** **Longitude:** -72.61289697
Image Direction: view north **Latitude:** 41.63558216
Notes: North looking view of asphalt driveway entering the Site



Photo ID: IMG_3961 **Date Taken:** **Longitude:** -72.6127702
Image Direction: view east **Latitude:** 41.63508229
Notes: View of existing orchard and adjacent treeline to remain along Northern edge of the Site

Project No. 24412 Address Old Maids Ln, Glastonbury, CT, 06073, USA
Project Name Old Maids Lane Report Project Area Photographs



Photo ID: IMG_3962 **Date Taken:**
Image Direction: view west **Latitude:** 41.63497134 **Longitude:** -72.61316943
Notes: View of existing asphalt driveway within the Site travel east to west along Northern edge of the Site



Photo ID: IMG_3963 **Date Taken:**
Image Direction: view west **Latitude:** 41.63452616 **Longitude:** -72.61342616
Notes: View of existing apple orchard & existing gentle sloping topography

Project No. 24412 Address Old Maids Ln, Glastonbury, CT, 06073, USA
Project Name Old Maids Lane Report Project Area Photographs



Photo ID: IMG_3964 **Date Taken:**
Image Direction: view west **Latitude:** 41.63445219 **Longitude:** -72.6143759
Notes: View of existing apple orchard & existing gentle sloping topography



Photo ID: IMG_3965 **Date Taken:**
Image Direction: view west **Latitude:** 41.63443847 **Longitude:** -72.61507294
Notes: View of approximate western termination of existing apple orchard & existing gentle sloping topography

Project No. 24412 Address Old Maids Ln, Glastonbury, CT, 06073, USA
Project Name Old Maids Lane Report Project Area Photographs



Photo ID: IMG_3966 **Date Taken:**
Image Direction: view west **Latitude:** 41.63377415 **Longitude:** -72.61866195
Notes: Existing terrain, site composition, & gentle slope west of apple orchard



Photo ID: IMG_3967 **Date Taken:**
Image Direction: view southeast **Latitude:** 41.63477878 **Longitude:** -72.61498054
Notes: View of approximate termination of asphalt driveway north of apple orchard areas

Project No. 24412 Address Old Maids Ln, Glastonbury, CT, 06073, USA
Project Name Old Maids Lane Report Project Area Photographs



Photo ID: IMG_3971 **Date Taken:**
Image Direction: view northwest **Latitude:** 41.63410901 **Longitude:** -72.61755072
Notes: View of existing erosion channel due to former quarry operations



Photo ID: IMG_3972 **Date Taken:**
Image Direction: view south **Latitude:** 41.63411408 **Longitude:** -72.61802436
Notes: View of former quarry operations & existing topography

Project No. 24412 Address Old Maids Ln, Glastonbury, CT, 06073, USA
Project Name Old Maids Lane Report Project Area Photographs



Photo ID: IMG_3973

Date Taken:

Image Direction: view south

Latitude: 41.63318604

Longitude: -72.6195054

Notes: View of existing gravel path at lower portion of the Site



Photo ID: IMG_3974

Date Taken:

Image Direction: view east

Latitude: 41.63348726

Longitude: -72.61856561

Notes: View of grade change at base of former quarry operations

Project No. 24412 Address Old Maids Ln, Glastonbury, CT, 06073, USA
Project Name Old Maids Lane Report Project Area Photographs



Photo ID: IMG_3975 **Date Taken:**
Image Direction: view southeast **Latitude:** 41.633743 **Longitude:** -72.61944305
Notes: Overall view of southwestern portion of the Site



Photo ID: IMG_3977 **Date Taken:**
Image Direction: view south **Latitude:** 41.63214645 **Longitude:** -72.61886965
Notes: View of existing gravel trail

Project No. 24412 Address Old Maids Ln, Glastonbury, CT, 06073, USA
Project Name Old Maids Lane Report Project Area Photographs



Photo ID: IMG_3978 **Date Taken:**
Image Direction: view north **Latitude:** 41.63249926 **Longitude:** -72.61878694
Notes: View north of wetland pond, existing vegetation & topography



Photo ID: IMG_3979 **Date Taken:**
Image Direction: view east **Latitude:** 41.63754472 **Longitude:** -72.61344327
Notes: View of existing driveway from Old Maids Lane, west of existing offsite farmland

Project No. 24412 Address Old Maids Ln, Glastonbury, CT, 06073, USA
Project Name Old Maids Lane Report Project Area Photographs



Photo ID: IMG_4100 **Date Taken:** **Longitude:** -72.61797109
Image Direction: view north **Latitude:** 41.63153624
Notes: View of assumed wetland outlet control structure



Photo ID: IMG_4101 **Date Taken:** **Longitude:** -72.61836328
Image Direction: view north **Latitude:** 41.63145775
Notes: View of assumed wetland outlet control structure