


\* The locations of the "Site Specific BMP's" are approximate. Also, the polygons indicating unbuffered stream segments and areas of potential septic failure are not to scale - the exaggerated size was necessary to make the sites visible given the scale of the map.





United States Department of Agriculture Natural Resources Conservation Service 344 Merrow Road, Suite A Tolland, CT 06084 www.ct.nrcs.usda.gov

An Equal Opportunity Provider and Employer