

- Sheep
- Chickens

Other Potential Sources of Waste

- 🗯 geese
- 🖇 dogs

seagulls


Water Quality Monitoring Points

Monitoring Points used in TMDL

Ancillary Monitoring Points

Perennial Water

✓ Coginchaug River



Waterbodies

Roads

— Secondary Roads

State Roads

Sub-Analysis Areas

Boundary

* The locations of the "Site Specific BMP's" are approximate. Also, the polygons indicating unbuffered stream segments and areas of potential septic failure are not to scale - the exaggerated size was necessary to make the sites visible given the scale of the map.

\bigcirc

United States Department of Agriculture Natural Resources Conservation Service 344 Merrow Road, Suite A Tolland, CT 06084 www.ct.nrcs.usda.gov

An Equal Opportunity Provider and Employer

