

**FIELD INSPECTION REPORT**

Inspection Date: February 21, 2020  
 Project Name: Spring Manor Farm  
 Project Number:  
 Building Name: Various Structures as listed below  
 Inspector: David Houseman Jr.

Scope: The office of FMBIO was asked to evaluate the structures for the feasibility of conservation of historical significant structures. The structures on the list were in various states of structural collapse and have been for a significant period of time. Photos of the structures were taken on each accessible side of the structure. The photos show unstable walls sections and structural decay with no lateral bracing which is subject to further failure from lateral forces such as wind. It is of the opinion of this Building Official that there is the possibility of imminent danger and of further collapse. The structures will be posted immediately at the entrance locations of the structures stating it is unlawful for entrance to such structure without permission from the Building Officials office.

The structures evaluated in this report were found on the Mansfield Town Property record ID# 7.12.5 ACC# 7125 are as follows:

- Slaughter House UConn #2191
- Livestock Barn UConn #7122
- Greenhouse UConn # 7120
- Dairy Processing House UConn #7106
- Dairy Barn and Silo UConn #7104
- Dairy Barn and Silo UConn #7105

C: Condition Compliant / N: Condition Noncompliant

Index #	ISSUE	C/N	CODE	SECT. #
1	<p><b>Observation:</b> Structures identified in the scope above were found to be in various states of collapse and are in imminent danger of further collapse. Photos of the field inspection were up loaded to the property file.</p> <p><b>Conclusion:</b> Signs for posting the property access to the structures were provided for posting as the Building code requires.</p>	N	2018 SBC	117.1

Remarks:

End of Report

Inspector Signature: \_\_\_\_\_