

56 Prospect Street P.O. Box 270 Hartford, CT 06103

Kathleen M. Shanley

Manager – Transmission Siting Tel: (860) 728-4527

August 7, 2017

Robert Stein, Chairman Connecticut Siting Council Ten Franklin Square New Britain, CT 06051

Re: Petition 1217

Bloomfield-Windsor Upgrades Project

Monthly Construction Progress Report – July 2017

#### Dear Chairman Stein:

On behalf of The Connecticut Light and Power Company doing business as Eversource Energy ("Eversource") and pursuant to Section 7.3 of the Development and Management Plan for the modifications to Rood Avenue, Bloomfield and North Bloomfield Substations and transmission lines 1777, 1779 and 1751, Eversource hereby provides a copy of the Monthly Construction Progress Report for the month of July 2017. Also included is a Project Construction Progress Table (see Attachment 1).

Please contact me at 860-728-4527 with any questions that you or other Council members may have on this report.

Sincerely,

Kathleen M. Shanley

Enclosure

Attachment 1 - Construction Progress Table July 2017



# Petition 1217 Bloomfield-Windsor Upgrades Project Monthly Construction Progress Report July 2017

#### **OVERHEAD TRANSMISSION LINE**

#### 1777/1779 Line Separation

Restoration is in progress.

#### 1777/1751 Line Separation

The remaining clearing and access road construction in this segment is within the Wintonbury Golf course. This work will be completed when the golf season has ended (after Thanksgiving).

The construction in this segment has been placed on hold due to outage constraints in the summer months. Construction will resume in September 2017.

#### 1779 Line Loop into Rood Avenue Substation

Final restoration of the areas outside Rood Avenue Substation is in progress. The landscaping on the north side of the substation is complete.

#### **SUBSTATIONS**

Construction at Bloomfield Substation is complete.

Construction at North Bloomfield Substation is complete.

At Rood Avenue Substation, in accordance with Condition 1e of the Decision, the installation of the landscaping on the northwest side of the substation is complete and the final restoration complete.

#### **MINOR D&M PLAN CHANGES**

There were no minor D&M Plan changes in the month of July 2017.



# **Bloomfield-Windsor Upgrades Project**

Monthly Construction Progress Report - Attachment 1 ~July 2017~

## **Substation Construction**

	Rood Avenue	Bloomfield	North Bloomfield
Site Development	95%	100%	100%
Foundation Installation	100%	100%	100%
Steel Erection	100%	100%	100%
Test Energization	100%	100%	100%
Total % Complete	99%	100%	100%

### **Transmission Line Construction**

		Bloomfield to Bloomfield Junc. (1777/1779)	Bloomfield Junc. to North Bloomfield (1777/1751)	1779 Line Loop into Rood Ave Substation
Civil Work	ROW Clearing (% Complete)	100%	90%	100%
	Access Roads & Construction Pads (% Complete)	100%	70%	100%
	Restoration (% Complete)	90%	0%	90%
	Total (% Complete)	97%	53%	97%
Foundation Install	Proposed Foundations	7	20	8
	Foundations Installed	7	20	8
	% Complete	100%	100%	100%
Structure Erection	Proposed Structures	16	53	8
	Structures Installed	16	35	8
	% Complete	100%	66%	100%
Wire Install / Relocation	Wire to be Installed / Relocated (ft)	8448	27984	500
	Installed / Relocated to Date (ft)	8448	18480	500
	% Complete	100%	66%	100%